PUBLIC UTILITIES COMMISSION 505 VAN NESS AVENUE SAN FRANCISCO, CA 94102-3298



June 3, 2013

CA2013-003

Mr. Ross Johnson, Area Manager, Regulatory AT&T 525 Market Street 19th Floor, #33 San Francisco, CA 94015-2727

Subject: Audit of AT&T Benicia, Fairfield and Vallejo

Dear Mr. Johnson:

On behalf of the Electric Safety and Reliability Branch of the California Public Utilities Commission, Ivan Garcia, Yusef Collins and Ryan Yamamoto conducted an audit of AT&T Solano County on April 8-10, 2013. The audit included a review of AT&T's maintenance records and inspections of AT&T's facilities.

During audit, we identified violations of one or more General Orders. A copy of the audit summary itemizing the violations is enclosed. Please advise me no later than July 12, 2013, by electronic or hard copy, of all corrective measures taken by AT&T California to remedy and prevent such violations.

If you have any questions concerning this audit you can contact, Ryan Yamamoto of my staff at (415) 703-2192 or ryan.yamamoto@cpuc.ca.gov.

Sincerely,

Ì

Raymond Fugere, P.E. Program and Project Supervisor Electric Safety and Reliability Branch Safety and Enforcement Division California Public Utilities Commission

Enclosures: CPUC Audit Summary

CC: Ivan Garcia, Utilities Engineer, CPUC Yusef Collins, Utilities Engineer, CPUC Ryan Yamamoto, Senior Utilities Engineer, CPUC

AUDIT SUMMARY

Company: AT&T California – Solano County Communication Infrastructure Provider Audit Date: April 8-10, 2013

| 1. | Location: | Solano County | |
|----|--|---|--|
| | Date Visited by CPUC: | 4/8-4/10/13 | |
| | Explanation of Violation(s): | | |
| | Inspection & Ma | aintenance Program Deficiencies | |
| | GO 95, Rule 80.1 | A-2, Statewide Inspection Requirements, states in part: | |
| | Each company shall prepare, follow, and modify as necessary, procedures for conducting patrol or detailed inspections for all of its Communication Lines throughout the State. Consistent with Rule 31.2, the type, frequency, and thoroughness of inspections shall be based upon | | |
| | GO 128, Rule 12. | 2, Design, Construction, and Maintenance, states in part: | |
| | Systems shall be maintained in such condition as to secure safety to workmen and the public in general. Systems and portions thereof constructed, reconstructed, or replaced on or after the effective date of these rules shall be kept in conformity with the requirement of these rules. | | |
| | GO 128, Rule 17.2, Inspection, states: | | |
| | Systems shall be inspected by the operator frequently and thoroughly for the purpose of ensuring [sic] that they are in good condition and in conformance with all applicable requirements of these rules. | | |
| | AT&T does not frequently and thoroughly inspect its facilities and document all GOs 95 and 128 violations, and does not perform inspections that encompass all of the overhead and underground lines. The frequency of inspections must be determined by AT&T at a level adequate enough to ensure that your facilities are in good condition and in compliance with GOs 95 and 128. AT&T's current inspection program does not meet the requirements of GO 95, Rule 80.1-A2 and GO 128, Rules 12.2 and 17.2. | | |

| Location: | Solano County | |
|---|--|--|
| Date Visited by CPUC: | 4/8-4/10/13 | |
| Explanation of Violation(s): | | |
| Corrective Action Deficiencies | | |
| GO 95, Rule 18-A1a, Resolution of Safety Hazard and General Order 95 Nonconformances, states: | | |
| Each company (including utilities and CIPs) is responsible for taking appropriate corrective action to remedy Safety Hazards and GO 95 nonconformances posed by its facilities. | | |
| their due date. An | nerous P3028 tags (corrective action tags) that were not corrected by n example is #AUT022319, a priority 1 tag, which is to be corrected mediated and reclassified to a lower within 72 hours but it took 36 e violation. | |
| | Date Visited by CPUC:CPUC:Explanation of VCorrective ActioGO 95, Rule 18-A NonconformanceGO 95, Rule 18-A NonconformanceCach colspan="2">Each col approp noncongAT&T's had num their due date. As or temporarily report | |

| 3. | Location: | 541 Curtola Parkway, Vallejo | |
|----|---|--|--|
| | Previous Visit by AT&T: | 3/6/2013 | |
| | Date Visited by CPUC: | 2/28/2013 | |
| | Explanation of Violation(s): | | |
| | Abandoned Servic | e Drop | |
| | GO 95, Rule 31.6, A | Abandoned Lines, states in part: | |
| | Lines or portions of lines permanently abandoned shall be removed by their owners so that such lines shall not become a public nuisance or a hazard to life or property | | |
| | The pole had an abandoned service drop. This violation was not documented when AT&T last inspected the pole. | | |
| | Broken Guy Wire | | |
| | GO 95, Rule 86. 2, states in part: | | |
| | Guys shall be attached to structures as nearly as practicable at the center of load. They shall be maintained taut and of such strength as to meet the safety factors of Rule 44. | | |
| | The pole had a brok inspected the pole. | ten guy wire. This violation was not documented when AT&T last | |

| 4. | Location: | 1589 Rayburn Court, Fairfield |
|----|--|-------------------------------|
| | Previous Visit by AT&T: | 3/12/2013 |
| | Date Visited by CPUC: | 4/9/2013 |
| | Explanation of Violation(s): | |
| | Clearance Between Wires | |
| | GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, states in part: | |
| | The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperature of 60° F. and no wind. | |
| | The pole had AT&T's service drop touching a service drop of a different CIP. This violation was not documented when AT&T inspected the pole. | |

| 5. | Location: | 325, 331 and 337 East Wyoming Street, Fairfield | |
|----|---|---|--|
| | Previous Visit by AT&T: | 3/15/2013 | |
| | Date Visited by CPUC: | 4/9/2013 | |
| | Explanation of Violation(s): | | |
| | Low Mainline Cat | ole and Service Drops | |
| | GO 95, Rule 37, Minimum Clearances of Wires above Railroads, Thoroughfares, Buildings, Etc., states in part: | | |
| | Clearances between overhead conductors, guys, messengers or trolley span wires and tops of rails, surfaces of thoroughfares or other generally accessible areas across, along or above which any of the former pass; also the clearances between conductors, guys, messengers or trolley span wires and buildings, poles, structures, or other objects, shall not be less than those set forth in Table 1, at a temperature of 60° F. and no wind. | | |
| | The poles had AT&T's mainline and service drops with vertical clearances that were low. This violation was not documented when AT&T inspected the pole. | | |

| 6. | Location: | 323 Texas Street, Fairfield |
|----|---|--|
| | Previous Visit by AT&T: | 1/18/2012 |
| | Date Visited by CPUC: | 4/9/2013 |
| | Explanation of Vio | olation(s): |
| | Missing Guy Guar | r <u>d</u> |
| | GO 95, Rule 86.9, Guy Marker (Guy Guard), states: A substantial marker of suitable material, including but not limited to metal or plastic, not less than 8 feet in length, shall be securely attached to all anchor guys. Where more than one guy is attached to an anchor rod, only the outermost guy is required to have a marker. The pole had an AT&T anchor guy without a guy guard. This violation was not documented when AT&T inspected the pole. <u>Abandoned Drop</u> GO 95, Rule 31.6, Abandoned Lines, states: | |
| | | |
| | | |
| | | |
| | | |
| | owners so life or pro abandone | portions of lines permanently abandoned shall be removed by their to that such lines shall not become a public nuisance or a hazard to operty. For the purposes of this rule, lines that are permanently ed shall be defined as those lines that are determined by their owner o foreseeable future use. |
| | The pole had an aba when AT&T inspec | andoned AT&T service drop. This violation was not documented cted the pole. |

| 7. | Location: | 1925 San Clemente Street, Fairfield | |
|----|--|-------------------------------------|--|
| | Previous Visit by AT&T: | 4/30/12 | |
| | Date Visited by CPUC: | 4/9/2013 | |
| | Explanation of Violation(s): | | |
| | Low Mainline Cat | <u>ble</u> | |
| | GO 95, Rule 37, Minimum Clearances of Wires above Railroads, Thoroughfares, Buildings, Etc., states in part: | | |
| | Clearances between overhead conductors, guys, messengers or trolley span wires and tops of rails, surfaces of thoroughfares or other generally accessible areas across, along or above which any of the former pass; also the clearances between conductors, guys, messengers or trolley span wires and buildings, poles, structures, or other objects, shall not be less than those set forth in Table 1, at a temperature of 60° F. and no wind. | | |
| | At this location, an AT&T mainline cable was low (measure at 7'7"). This violation was not documented when AT&T inspected the pole. Also, this was a closed tag location and supposedly had been corrected but the violation was still present. Please explain why the violation was not corrected? | | |

| 8. | Location: | 341 Cottonwood Street, Vallejo |
|----|---|--------------------------------|
| | Previous Visit by AT&T: | 9/28/2010 |
| | Date Visited by CPUC: | 4/9/2013 |
| | Explanation of Violation(s): | |
| | Slack Guy Wire | |
| | GO 95, Rule 86. 2, states in part: | |
| | Guys shall be attached to structures as nearly as practicable at the center of load. They shall be maintained taut and of such strength as to meet the safety factors of Rule 44. | |
| | The pole had a slack guy wire. This violation was not documented when AT&T last inspected the pole. Also, please provide me with when this location was last visited before 4/9/2013. | |

| 9. | Location: | 689 East "N" Street, Benicia | | |
|----|---|--|--|--|
| | Previous Visit by AT&T: | 3/27/2013 | | |
| | Date Visited by CPUC: | 4/9/2013 | | |
| | Explanation of Vie | Explanation of Violation(s): | | |
| | Insufficient Cleara | Insufficient Clearance Between Communication Conductor and Electric Down Guy | | |
| | <u>Wire</u> | Wire | | |
| | GO 95, Rule 38, Ta | GO 95, Rule 38, Table 2, Case 19C, requires that: | | |
| | Guys and span wires passing communication conductors (including service drops) supported on the same pole must maintain a three (3) inch radial separation. | | | |
| | The pole had a communication conductor in contact with a guy wire. This violation was not documented when AT&T last inspected the pole. | | | |

| 10. | Location: | 510 East "N" Street, Benicia | |
|-----|--|------------------------------|--|
| | Previous Visit by AT&T: | 3/27/2013 | |
| | Date Visited by CPUC: | 4/9/2013 | |
| | Explanation of Violation(s): | | |
| | Clearance Between Wires | | |
| | GO 95, Rule 38, Minimum Clearances of Wires from Other Wires, states in part: | | |
| | The minimum vertical, horizontal or radial clearances of wires from other wires shall not be less than the values given in Table 2 and are based on a temperature of 60° F. and no wind. | | |
| | The pole had AT&T's service drop touching a service drop of a different CIP. This violation was not documented when AT&T inspected the pole. | | |

Recommendation

Preservation of Records Issue

GO 95, Rule 18-A1b, Resolution of Safety Hazard and General Order 95 Nonconformances, states:

Upon completion of the corrective action, the company's records shall show, with sufficient detail, the nature of the work, the date, and the identity of persons performing the work. These records shall be preserved by the company for at least ten (10) years and shall be made available to Commission staff upon 30 days notice.

AT&T staff stated that some records may be only retained for five (5) years in the electronic system.