

Table I – PGE Determination Summary of B/ TCI Radiographic Assessment Accuracy

| Item# | BV Sample # | Weld ID   | BV declared Rej. imperfection(s) | PGE quantitative analysis summary   | BV conclusion found to be : |
|-------|-------------|-----------|----------------------------------|---|-----------------------------|
| 1     | 28          | 163-2 W18 | Burn Through                     | BV interpret & measurement error – no defect  | INCORRECT                   |
| 2     | 23          | 163-1 V8  | Burn Through                     | BV interpret & measurement error – no defect  | INCORRECT                   |
| 3     | 516         | 41-1W5    | Burn Through                     | BV interpret & measurement error – no defect  | INCORRECT                   |
| 4     | 342         | 175-1 T13 | Internal Concavity               | BV measurement <del>close call</del> , but no defect  | Marginal - incorrect        |
| 5     | 425         | 184-21W14 | Internal Concavity               | BV measurement error close call, but no defect  | Marginal - incorrect        |
| 6     | 2           | 3-11W88   | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 7     | 4           | 3-17 W58  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 8     | 5           | 3-27 V95  | External Undercut                | BV code application & measure error – no defect   | INCORRECT                   |
| 9     | 16          | 74-1 WC-3 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 10    | 26          | 108-4W35  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 11    | 70          | 131-3 V91 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 12    | 85          | 133-2W71  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 13    | 248         | 155-32W88 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 14    | 270         | 160-4 W5  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 15    | 326         | 173-6 V14 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 16    | 330         | 173-7 W14 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 17    | 333         | 174-1 V8  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 18    | 337         | 174-2 W5  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 19    | 338         | 174-3V1   | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 20    | 339         | 174-3 W2  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 21    | 366         | 180-11W40 | External Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 22    | 406         | 180-9W18  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 23    | 412         | 182-5W16  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 24    | 414         | 183-1V4   | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 25    | 421         | 183-19 W6 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 26    | 430         | 184-24V22 | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 27    | 475         | 27-2 V8   | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 28    | 477         | 29-2 W12  | Internal Undercut                | BV interpret & measurement error – no defect  | INCORRECT                   |
| 29    | 484 (2)     | 3-15W53   | 1. Internal Undercut,<br>2. Slag | BV interpret & measurement error – no defect<br>BV interpretation error – weld profile, no defect | INCORRECT                   |


PGE Applied Technology Services Report: 413.61-14.67, Appendix IV –  
 Note: This table links to data in Appendix I, & addresses 49 separate welds

Table I – R&E Determination Summary of B/ TCI Radiographic Assessment Accuracy

| Item# | B/V Sample # | Weld ID    | B/V declared Rej. imperfection(s)   | R&E quantitative analysis summary   | B/V conclusion found to be:            |
|-------|--------------|------------|---|---|--|
| 30    | 653 (2)      | 87A-11 W14 | 1. Internal Undercut<br>2. Incomp Pen - IPD                               | BV interpret & measurement error – no defect<br>BV code interpretation error for IPD length   | INCORRECT                              |
| 31    | 19           | 742 WC1    | Incomp. Pen. IPD/ IP  | BV code interpret & sizing error – no   | INCORRECT                              |
| 32    | 15           | 106-1W2    | Incomp. Pen – IPD   | BV measurement error close call, but no defect  | Marginal - incorrect                   |
| 33    | 68           | 131-3W89   | Incomplete Pen. IP  | BV interp. error & failure to follow readersheet  | INCORRECT                              |
| 34    | 71           | 131-3 W85  | Incomp. Pen – IPD   | BV unambiguous interpretation error   | INCORRECT                              |
| 35    | 307          | 168-1 W2   | Incomp. Pen - IP  | BV ambiguous and incomplete citation  | Marginal - incorrect                   |
| 36    | 394 (3)      | 180-16 W1  | 1. Incomp. Pen – IP<br>2. Incomplete Fusion IF<br>3. Incomplete Fusion IF | BV incorrect decision on noted info only weld<br>BV incorrect decision on noted info only weld<br>BV incorrect decision on noted info only weld | INCORRECT                              |
| 37    | 45           | 27-2 W8    | Incomp. Pen – IP  | BV interpret & measurement error – no   | INCORRECT                              |
| 38    | 65           | 80-3W2     | Incomp Pen – IPD  | BV correct interpretation, but weld was not to code, though incorrectly noted pre-repair  | Correct but this is a not to code weld |
| 39    | 638          | 87-14 W2   | Incomp. Pen – IP  | BV measurement close call, but no defect  | Marginal - incorrect                   |
| 40    | 39           | 144-2WT1   | Slag  | BV interpretation error – no Rej. Slag defect   | INCORRECT                              |
| 41    | 27           | 163-2 W24  | Slag  | BV interpretation error – no Rej slag def   | INCORRECT                              |
| 42    | 47           | 126-3 W18  | Slag  | BV interpretation – film artifacts, no s  | INCORRECT                              |
| 43    | 156          | 152-6 W07  | Porosity  | BV interpretation – No rejectable Porosit   | INCORRECT                              |
| 44    | 20           | 74-4 W1    | Incomplete Fusion   | BV interpretation error – no rejectable   | INCORRECT                              |
| 45    | 155          | 152-6W06   | Incomplete Fusion   | BV interpretation error – no IF defect  | INCORRECT                              |
| 46    | 433          | 184-29W81  | Incomplete Fusion   | BV interpretation error – film condition/artifacts  | INCORRECT                              |
| 47    | 459          | 24-1 WC2   | Incomplete Fusion   | BV reader sheet Interp. Error   | INCORRECT                              |
| 48    | 460          | 24-3WT1    | Incomplete Fusion   | BV interpret & measurement error – no defect  | INCORRECT                              |
| 49    | 512          | 39-1 W27   | Incomplete Fusion   | BV Interp./Mnt. close call, but no defect   | Marginal - incorrect                   |

Note: This summary table contains R&E's analysis of each instance where throughout the various sections and versions of B/V's reports, B/V has reported a "Defect", "Rejectable non-compliant imperfection" item within the weld. While B/V has reported a total of welds in their latest summary, in the body of the reports, 49 welds are identified as non-compliant weld imperfections. R&E has reviewed all of these, and found no code discrepancies.

Summary of BV Assessment Performance on all welds cited with "non-compliant imperfections"



R&E Applied Technology Services Report: 413.61-14.67, Appendix IV –  
Note: This table links to data in Appendix IX 1, & addresses 49 separate welds

■ Incorrect interpretation  
■ Marginal, but incorrect interpretation  
■ Agree, but citation is on a not to code weld