



6100 Neil Road, P.O. Box 10100, Reno, Nevada 89520-0024

---

June 28, 2001

Wesley M. Franklin  
Executive Director  
California Public Utilities Commission  
505 Van Ness Avenue  
San Francisco, CA 94102

Dear Mr. Franklin:

Attached are copies of the Annual GO165 Reports for Sierra Pacific Power Co. These reports are submitted in compliance with Section III of GO 165. Unlike prior years, Sierra is only providing two separate reports for 2000 inspections and 2000-2001 repairs. The report for Yerington/Walker is now included within the report for Carson/Markleville, and the Tahoe District report is still separate. This reporting comports to location of maintenance records and responsibilities.

If additional information is required, please do not hesitate to call me at (775) 834-4778.

Sincerely,

A handwritten signature in black ink that reads "Stan Bennett". The signature is written in a cursive style with a large, prominent "S" and "B".

Stan Bennett  
Regulatory Services

Attachments

Cc: Wade McCartney  
Energy Division Compliance Reports Room (4005)

**SIERRA PACIFIC POWER COMPANY  
TAHOE DISTRICT - ANNUAL GO 165 REPORT**

**YEAR 2000**

**YEAR 2001**

All Inspected Circuits	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% of Total Units for Repair	# of Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
<b>Transformers</b>									
Overhead	465	465	0	0	0	0	0	0	0
Underground	1	1	1	100%	1	100%	0	0	0
Padmounted	90	90	1	1%	1	100%	0	0	0
<b>Switching/Protective Devices</b>									
Overhead	434	434	0	0	0	0	0	0	0
Underground	0	0	0	0	0	0	0	0	0
Padmounted	30	30	0	0	0	0	0	0	0
<b>Regs./Capacitors</b>									
Overhead	18	18	1	6%	0	0	1	0	0
Underground	0	0	0	0	0	0	0	0	0
Padmounted	0	0	0	0	0	0	0	0	0
<b>Distribution Conductors &amp; Cable Miles</b>	146 mi.	146mi							
Pole Line Hardware, Infractions, Etc.	3047	3047	158*	5%*	117*	74%*	41*	0*	0*
Vaults, Boxes & Manholes	61	61	1	2%	1	100%	0	0	0
Junction Enclosures	3	3	0	0	0	0	0	0	0
<b>Wood Poles</b>									
Wood Poles Inspected	3047	3047	*	*	*	*	*	*	*
Wood Poles Intrusively Inspected	2861	2861	140	5%	122	87%	18	18	100%

**SIERRA PACIFIC POWER COMPANY  
TAHOE DISTRICT - ANNUAL GO 165 REPORT**

YEAR 1999

YEAR 2000

All Inspected Circuits	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% of Total Units for Repair	# of Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
<b>Transformers</b>									
Overhead	1133	1133	2	.18%	2	100%	0		
Underground	43	43	2	4%	2	100%	0		
Padmounted	152	152	1	.66%	1	100%	0		
<b>Switching/Protective Devices</b>									
Overhead	767	767	1	.13%	1	100%	0		
Underground	0						0		
Padmounted	14	14	0				0		
<b>Regs./Capacitors</b>									
Overhead	8	8	0				0		
Underground	0						0		
Padmounted	0						0		
<b>Distribution Conductors &amp; Cable Miles</b>	158.5 mi.								
Pole Line Hardware, Infracions, Etc.	3486	3486	546	15.7%	243	44.5%	303	303	100%
Vaults, Boxes & Manholes	55	55	2	3.6%	2	100%	0		
Junction Enclosures	2	2	0				0		
Wood Poles									
Wood Poles Inspected	3486	3486	0				0		
Wood Poles Intrusively Inspected	2655	2850	205	7.2%	205	100%	0		

**SIERRA PACIFIC POWER COMPANY  
ANNUAL GO165 REPORT - CARSON/MARKLEVILLE DISTRICT**

	Year 2001						Year 2000		
	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% Total Units for Repair	# Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
<b>All Inspected Circuits</b>									
<b>Transformers</b>									
Overhead	0	0	0	0%	0	0%	0		
Underground									
Padmounted	0	0	0	0%	0	0%	0		
<b>Switching/Protective Devices</b>									
Overhead	0	0	0	0%	0	0%	0		
Underground									
Padmounted									
<b>Regs/Capacitors</b>									
Overhead	0	0	0	0%	0	0%	0		
Underground									
Padmounted									
<b>Distribution Conductors &amp; Cable Miles</b>									
Pole Line Hardware, Infractions, Etc.	0	0	0	0%	0	0%	0	85	100%
Vaults, Boxes & Manholes	0	0	0	0%	0	0%	0		
Junction Enclosers	0	0	0	0%	0	0%	0		
<b>Wood Poles</b>									
Wood Poles Inspected	0	0	0	0%	0	0%	0		
Wood Poles Intrusively Inspected	1000	1007	64	6%	7 (1)	10%			

**Notes:**

- 1) These poles were priority replacements and have been replaced as of this reporting date. The balance of the poles are to be stubbed and will be done by year end.

SIERRA PACIFIC POWER COMPANY  
ANNUAL GO165 REPORT - CARSON DISTRICT  
as of July 1, 2000

	Year 1999					Year 2000			
	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% Total Units for Repair	# Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
<b>All Inspected Circuits</b>									
Transformers									
Overhead	0	0	0	0%	0	0%	0		
Underground									
Padmounted	0	0	0	0%	0	0%	0		
Switching/Protective Devices									
Overhead	0	0	0	0%	0	0%	0		
Underground							0		
Padmounted									
Regs/Capacitors									
Overhead	0	0	0	0%	0	0%	0		
Underground									
Padmounted									
Distribution Conductors & Cable Miles	0	0	0	0%	0	0%	0		
Pole Line Hardware, Infractons, Etc.	0	0	0	0%	0	0%	85 (1)		
Vaults, Boxes & Manholes	0	0	0	0%	0	0%	0		
Junction Enclosers	0	0	0	0%	0	0%	0		
Wood Poles									
Wood Poles Inspected	0	0	0	0%	0	0%	0		
Wood Poles Intrusively Inspected									

**Notes:**

1. These are priority three items left to repair from 1998 inspections