

June 28, 2005

Colleen Sullivan
California Public Utilities Commission
505 Van Ness Avenue
San Francisco, CA 94102

Dear Ms. Sullivan:

Attached is a copy of the Annual GO 165 Report for Sierra Pacific Power Company. This report is submitted in compliance with Section III of GO 165.

If additional information is required, please do not hesitate to call me at (775) 834-6353.

Sincerely,

Gene Williams
Principal Financial Analyst

Attachment

**Annual GO 165 Report
Sierra Pacific Power Company**

	Year 2004						Year 2005		
	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% Total Units for Repair	# Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
All inspected Circuits									
Transformers									
Overhead	667	667	82	12.3%	12	14.6%	70	0	
Underground	60	60	25	41.7%	0	0.0%	25	0	
Padmounted	190	190	11	5.8%	8	72.7%	3	0	
Switching/Protective Devices									
Overhead	891	891	5	0.6%	1	20.0%	4	0	
Underground	0	0	0		0		0	0	
Padmounted	20	20	0	0.0%	0		0	0	
Regs/Capacitors									
Overhead	6	6	1	16.7%	1	100.0%	0	0	
Underground	0	0	0		0		0	0	
Padmounted	0	0	0		0		0	0	
Distribution Conductors & Cable Miles	139.3	139.3							
Pole Line Hardware, Infractions, Etc.	2875	2875	461	16.0%	250	54.2%	211	0	
Vaults, Boxes & Manholes	75	75	3	4.0%	3	100.0%	0	0	
Junction Enclosers	14	14	1	7.1%	1	100.0%	0	0	
Wood Poles									
Wood Poles Inspected	2731	2731	36	1.3%	0	0.0%	36	0	
Wood Poles Intrusively Inspected	1906	1906	61	3.2%	22	36.1%	39	0	