

June 27, 2007

Colleen Sullivan
California Public Utilities Commission
505 Van Ness Avenue
San Francisco, CA 94102

Dear Ms. Sullivan:

Attached is a copy of the Annual GO 165 Report for Sierra Pacific Power Company.
This report is submitted in compliance with Section III of GO 165.

If additional information is required, please do not hesitate to call me at (775) 834-4686.

Sincerely,



Debbie Rice
Case Manager
Rates and Regulatory Affairs

Attachment

TAHOE DISTRICT ANNUAL GO 165 REPORT
YEAR 2007

YEAR 2008

All Inspected Circuits	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% of Total Units for Repair	# of Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
Transformers									
Overhead	202	202	3	1.5%	22	*	0	0	
Underground	7	7	0	0	0	0	0	0	
Padmounted	505	505	23	4.6%	67	*	0	0	
Switching/Protective Devices									
Overhead	67	67	0	0	0	0	0	0	
Underground	2	2	1	50%	1	100%	0	0	
Padmounted	51	51	1	2%	1	100%	0	0	
Regs./Capacitors									
Overhead	0	0	0	0	0	0	0	0	
Underground	0	0	0	0	0	0	0	0	
Padmounted	0	0	0	0	0	0	0	0	
Distribution Conductors & Cable Miles	45	45							
Pole Line Hardware, Infractions, Etc.	4260	4260	228	5.4%	578	*	0	0	
Vaults, Boxes & Manholes	58	58	0	0	0	0	0	0	
Junction Enclosures	38	38	2	5.2%	0	0%	2	0	
Wood Poles									
Wood Poles Inspected	4260	4260							
Wood Poles Intrusively Inspected	824	824							

* These percentages are over 100% because we were completing repairs from the 2006 Inspections.