

June 30, 2010

David Lee, Utility Engineer
California Public Utilities Commission
505 Van Ness Avenue
San Francisco, CA 94102

Dear Mr. Lee:

Attached is a copy of the Annual GO 165 Report for Sierra Pacific Power Company.
This report is submitted in compliance with Section III of GO 165.

If additional information is required, please do not hesitate to call me at (775) 834-4686.

Sincerely,



Debbie Rice
Case Manager
Rates and Regulatory Affairs

Attachment

Sierra Pacific Power Company
ANNUAL GO 165 REPORT
 (California Service Territory)

Year - 2009

Year - 2010

All Inspected Circuits		Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% of Total Units for Repair	# of Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired To Date	% of Units Repaired To Date
Transformers										
Overhead		913	913	123	13.5%	0	0.0%	123	0	0.0%
Underground		153	153	66	43.1%	133	201.5%	-67	0	0.0%
Padmounted		545	545	170	31.2%	20	11.8%	150	37	24.7%
Switching / Protective Devices										
Overhead		534	534	35	6.6%	0	0.0%	35	0	0.0%
Underground		3	3	1	33.3%	0	0.0%	1	0	0.0%
Padmounted		73	73	62	84.9%	2	3.2%	60	4	6.7%
Regulators / Capacitors / Reclosures										
Overhead		11	11	0	0.0%	0	0.0%	0	0	0.0%
Underground		0	0	0	0.0%	0	0.0%	0	0	0.0%
Padmounted		1	1	1	100.0%	0	0.0%	1	0	0.0%
Distribution Conductors & Cable Miles										
		62.2	62.2	~	~	~	~	~	~	~
Pole Line Hardware, Infractions, etc.										
		3474	3474	421	12.1%	1276	303.1%	-855	425	-49.7%
Vaults, Boxes & Manholes										
		226	226	42	18.6%	4	9.5%	38	1	2.6%
Junction Enclosures										
		28	28	5	17.9%	2	40.0%	3	3	100.0%
Wood Poles										
Wood Poles Inspected		3474	3474	~	~	~	~	~	~	~
Wood Poles Intrusively Inspected		2734	2734	~	~	~	~	~	~	~