

The **existing view** to the east-northeast toward the San Vicente Road Transition Alternative. This view is from eastbound San Vicente Road, just west of the cable pole location. This alternative would include the placement of two cable poles in a clearing just north of San Vicente Road and just west of an existing transmission line as indicated above. The structure location is substantially screened by surrounding oak trees though an existing transmission structure (visible in the image above as a structurally complex, industrial feature) is noticeable.

Key Viewpoint 38
San Vicente Road
Transition Alternative

Existing View

SUNRISE POWERLINK PROJECT ALTERNATIVES Visual Resources Figure D.3-40