


**Attachment A.8: C157 Map Overview**

**CNF Preliminary Plan of Development**

- Wood-to-Steel Replacement
- Similar Actions Shown with Dashed Line
- United States Forest Service
- Map Extent
- Stream
- Lake



Z:\Projects\SDGE\_CNF\_ESRP\XDS\POD\Detailed\_Route\_Maps\Distribution\C157\_Map\_Overview.mxd 8/2/2012

Source: SDG&E, 2012; USFS, 2012; CPAD 1.7, 2011 GreenInfo Network