


Attachment B.8: C157 Map Overview

CNF Revised Plan of Development

- Wood-to-Steel Replacement
- Similar Actions Shown with Dashed Line
- United States Forest Service
- Map Extent
- Stream
- Lake



Z:\Projects\SDGE_CNF_ESRP\XDS\IPOD\Revised_POD_April_2013\Detailed_Route_Maps\Distribution\C157_Map_Overview.mxd 4/18/2013

Source: SDG&E, 2012; USFS, 2012; CPAD 1.7, 2011 GreenInfo Network