

Reference	Line	Milepoint	Segment	Primary Driver for "cut-out"	Identifying Group	Date Identified	Comments	Chain of Custody Document	Photos
#6	132	42.56	189	Short section	Camera Team	1-Jun-11	This section contains TWO girth welds which have characteristics of being field welds. One weld exhibits lack of penetration. This sample was removed prior to any hydro-testing performed.	Yes -- Piece # L-132-42.56-1 Milpitas Terminal / Field to EWI	Yes
#9	132	42.34	189	External Anomaly	Camera Team	29-May-11	Visual inspection by PLE and on-site USRB staff identified	Yes -- Piece L-132-42.34-1A	Yes

Comments: There appears to be some confusion about the number of samples currently with EWI for testing. Currently only 3 samples (custody chain reference #6 & #9 are in their possession for testing)  
Reference #6 has TWO girth welds contained within one sample for testing