

From: Cherry, Brian K
Sent: 10/24/2011 11:21:03 AM
To: 'pac@cpuc.ca.gov' (pac@cpuc.ca.gov); 'frl@cpuc.ca.gov' (frl@cpuc.ca.gov)
Cc: 'mlc@cpuc.ca.gov' (mlc@cpuc.ca.gov)
Bcc:
Subject: FW: T-117 CPUC Failure Report.

FYI

From: Garber, Stephen (Law)
Sent: Monday, October 24, 2011 11:18 AM
To: Cherry, Brian K; Horner, Trina; Ramaiya, Shilpa R; Hartman, Sanford (Law); Malkin, Joseph M (Law); [Redacted] Foley, Beth
Subject: FW: T-117 CPUC Failure Report.

The attached failure report was just sent to the CPUC.

Line 300B

34 inch line

DSAW

757 MAOP

Class 1

Failed at 998 psig, or 131.8% of MAOP or 94.9% SMYS

From: Campbell, Ben (NRD)
Sent: Monday, October 24, 2011 11:15 AM
To: [Redacted]
Subject: Fw: T-117 CPUC Failure Report.

FYI

From: [Redacted]
Sent: Monday, October 24, 2011 10:34 AM
To: [Redacted]
Cc: Campbell, Ben (NRD); Cabral, Mark; Mannie, Joel C; Moreland, Chauna; [Redacted] Johnson, Kirk; Ittner, Mary Ellen; [Redacted]
Subject: T-117 CPUC Failure Report.

Redacted

Attached is the T-117 Hydrotest CPUC failure report for your review and submittal.
<<T-117FailureCPUCFailureReport10.24.2011.pdf>>

Redacted

Hydrotest Team
Pacific Gas and Electric CO.
350 N. Wiget Ln. Suite 250
Walnut Creek, CA 94598

Redacted

Prepared under Attorney Client Privilege, Confidential.