

From: Cherry, Brian K  
Sent: 10/24/2011 11:21:03 AM  
To: 'pac@cpuc.ca.gov' (pac@cpuc.ca.gov); 'frl@cpuc.ca.gov' (frl@cpuc.ca.gov)  
Cc: 'mlc@cpuc.ca.gov' (mlc@cpuc.ca.gov)  
Bcc:  
Subject: FW: T-117 CPUC Failure Report.

FYI

**From:** Garber, Stephen (Law)  
**Sent:** Monday, October 24, 2011 11:18 AM  
**To:** Cherry, Brian K; Horner, Trina; Ramaiya, Shilpa R; Hartman, Sanford (Law); Malkin, Joseph M (Law); [Redacted] Foley, Beth  
**Subject:** FW: T-117 CPUC Failure Report.

The attached failure report was just sent to the CPUC.

Line 300B

34 inch line

DSAW

757 MAOP

Class 1

Failed at 998 psig, or 131.8% of MAOP or 94.9% SMYS

**From:** Campbell, Ben (NRD)  
**Sent:** Monday, October 24, 2011 11:15 AM  
**To:** [Redacted]  
**Subject:** Fw: T-117 CPUC Failure Report.

FYI

**From:** [Redacted]  
**Sent:** Monday, October 24, 2011 10:34 AM  
**To:** [Redacted]  
**Cc:** Campbell, Ben (NRD); Cabral, Mark; Mannie, Joel C; Moreland, Chauna; [Redacted] Johnson, Kirk; Ittner, Mary Ellen; [Redacted]  
**Subject:** T-117 CPUC Failure Report.

Redacted

Attached is the T-117 Hydrotest CPUC failure report for your review and submittal.  
<<T-117FailureCPUCFailureReport10.24.2011.pdf>>

Redacted

**Hydrotest Team**  
**Pacific Gas and Electric CO.**  
**350 N. Wiget Ln. Suite 250**  
**Walnut Creek, CA. 94598**

Redacted

Prepared under Attorney Client Privilege, Confidential.