

From: Campbell, Ben (NRD)
Sent: 2/29/2012 6:04:21 PM
To: 'Shori, Sunil' (sunil.shori@cpuc.ca.gov)
Cc: Ramaiya, Shilpa R (/o=PG&E/ou=Corporate/cn=Recipients/cn=SRRd)
Bcc:
Subject: FW: T30_L132_B-West_(MP-13.95)

Sunil:

Here is the H-form for the section of Line 132 (m.p. 13.95) with corrosion that was discussed in the testimony of [Redacted] I have confirmed that the only two sleeves installed in all the tests we completed in 2011 were at this location and the location where the leak occurred on Line 132 at m.p. 15.003. Do you want me to send you the H-form for the leak location on Line 132 as well? I know I have sent it to you in the past.

Ben Campbell

From: [Redacted]
Sent: Wednesday, February 15, 2012 11:50 AM
To: [Redacted]
Cc: [Redacted]
Subject: T30_L132_B-West_(MP-13.95)

--

Regards,

Redacted

Senior NDE Technician
GE Energy
Inspection Services

Redacted