

From: Shori, Sunil
Sent: 2/29/2012 6:25:11 PM
To: Campbell, Ben (NRD)
(/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=BCC3)
Cc: Ramaiya, Shilpa R (/o=PG&E/ou=Corporate/cn=Recipients/cn=SRRd)
Bcc:
Subject: RE: T30_L132_B-West_(MP-13.95)

Ben,

Thanks for the H-Form and I would appreciate it if you could send the form for M.P. 15.003, as well. One other thing, I request PG&E please confirm if all welding procedures used by contractors on the hydro-tests were strictly limited to PG&E procedures only, or if any non-PG&E procedures were accepted and/or used in any of the welds.

Thanks, Ben.

Sunil

From: Campbell, Ben (NRD) [mailto:BCC3@pge.com]
Sent: Wednesday, February 29, 2012 6:04 PM
To: Shori, Sunil
Cc: Ramaiya, Shilpa R
Subject: FW: T30_L132_B-West_(MP-13.95)

Sunil:

Here is the H-form for the section of Line 132 (m.p. 13.95) with corrosion that was discussed in the testimony of Redacted I have confirmed that the only two sleeves installed in all the tests we completed in 2011 were at this location and the location where the leak occurred on Line 132 at m.p. 15.003. Do you want me to send you the H-form for

the leak location on Line 132 as well? I know I have sent it to you in the past.

Ben Campbell

From: [Redacted] **On Behalf Of** [Redacted]
Sent: Wednesday, February 15, 2012 11:50 AM
To: [Redacted]
Cc: [Redacted]
Subject: T30_L132_B-West_(MP-13.95)

--

Regards,

[Redacted]
Senior NDE Technician
GE Energy
Inspection Services

[Redacted]