

From: Campbell, Ben (NRD)
Sent: 2/29/2012 6:42:22 PM
To: 'Shori, Sunil' (sunil.shori@cpuc.ca.gov)
Cc: Ramaiya, Shilpa R (/o=PG&E/ou=Corporate/cn=Recipients/cn=SRRd)
Bcc:
Subject: RE: T30_L132_B-West_(MP-13.95)

Hi Sunil:

Here is the other H-form for MP 15.003. PG&E includes PG&E welding procedures in the construction package provided to the contractor and no non-PG&E procedures should have been used. Also, our engineering team did not qualify any non-PG&E welding procedures for hydrotest work so none should have been used.

Ben Campbell

From: Shori, Sunil [mailto:sunil.shori@cpuc.ca.gov]
Sent: Wednesday, February 29, 2012 6:25 PM
To: Campbell, Ben (NRD)
Cc: Ramaiya, Shilpa R
Subject: RE: T30_L132_B-West_(MP-13.95)

Ben,

Thanks for the H-Form and I would appreciate it if you could send the form for M.P. 15.003, as well. One other thing, I request PG&E please confirm if all welding procedures used by contractors on the hydro-tests were strictly limited to PG&E procedures only, or if any non-PG&E procedures were accepted and/or used in any of the welds.

Thanks, Ben.

Sunil

From: Campbell, Ben (NRD) [mailto:BCC3@pge.com]
Sent: Wednesday, February 29, 2012 6:04 PM
To: Shori, Sunil
Cc: Ramaiya, Shilpa R
Subject: FW: T30_L132_B-West_(MP-13.95)

Sunil:

Here is the H-form for the section of Line 132 (m.p. 13.95) with corrosion that was discussed in the testimony of [Redacted] and [Redacted]. I have confirmed that the only two sleeves installed in all the tests we completed in 2011 were at this location and the location where the leak occurred on Line 132 at m.p. 15.003. Do you want me to send you the H-form for the leak location on Line 132 as well? I know I have sent it to you in the past.

Ben Campbell

From: [Redacted] **On Behalf Of** [Redacted]
Sent: Wednesday, February 15, 2012 11:50 AM
To: [Redacted]; [Redacted]
Cc: [Redacted]
Subject: T30_L132_B-West_(MP-13.95)

--

Regards,

Redacted

Senior NDE Technician
GE Energy
Inspection Services

Redacted