

Land & Environmental Management Pilot

	Gas Transmission Line 132 Encroachment Pilot Projects	
Redacted		
	· .	A THE PARTY OF THE
		The state of the s
		The second secon
		A Delining to the control of the con

Final Report: Redacted

edacted	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Santa Clara
Depth of Cover	54" to 100"
Pipeline:	132
Encroachment Type:	House, Shed and Garage

Summary:


The main house is within the easement and over the pipeline. The expanded garage overhang is within the easement and appears to be over the pipeline. The small shed addition is within the easement and the overhang appears to be over the pipeline.

Final Report: Redacted

	Redacted	minimum year, and an analysis of the control of the	 W WEEK A
	Cadeced		
			all control of the co
			SAPPLE STATE OF THE STATE OF TH
			H
li e			T-Proposoooo

internal arate for alseassion parposes only

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report Redacted




Standing on the line looking west.



Standing on the line looking to the east.

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report: Redacted



Main House is over the line.



Deck is over the top of the line.

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report Redacted



Second House (expanded garage) Overhang within the easement and over the pipe.

Final Report: Redacted

Redacted	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Santa Clara
Depth of Cover	42"
Pipeline:	132
Encroachment Type:	Shed

Summary

Building structure and concrete patio with cover is within easement and over pipeline.

Final Report:	Redacted
---------------	----------


Redacted			




Standing on the line looking west from the covered patio



Standing on the line looking to the east.



Standing on the line looking to the west.



Shed is over the top of the line.



Patio with overhang is over the top of the line.

Final Report:	Redacted	

edacted	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Santa Clara
Depth of Cover	52"
Pipeline:	132
Encroachment Type:	Mobile Home

Summary:

Property boundaries are not yet resolved as there is little monumentation in the area and to resolve the boundary would likely require an extensive survey of the property and surrounding areas. The easement lines are not yet shown on the map. The edge of the mobile home is .73' away from the pipeline and the concrete patio is .25' away from pipeline. There are utility hookups on the adjacent lot that may be encroaching into the easement.


Final	Report:	Redacted
--------------	---------	----------

Redacted		i mai neport.	
	Redacted		

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report: Redacted




Standing on the line looking west.




Standing on the line looking to the east.

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report: Redacted



Mobile home is within the easement.



Utility hooks ups are within the easement.

Final Report: Redacted

Redacted

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Santa Clara
Depth of Cover	40"
Pipeline:	132
Encroachment Type:	Shed


Summary:

Storage shed is within the easement and over the pipeline. The edge of the house is .3' into the easement and not over the pipeline

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report: 791 San Lucas Ave, Mountain View

Redacted		

Final Report: Redacted



Standing on the line looking northwest



Standing on the line looking to the southeast

Final Report: Redacted



Shed is within the easement area.



Shed is over the top of the line.

Final Report: Redacted

edacted	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Santa Clara
Depth of Cover	40"
Pipeline:	132
Encroachment Type:	House

Summary:

The house encroaches 1.4' into the easement and is not over the pipeline.

Report of Findings for Line 132 Gas Pipeline Encroachment Pilot Program Final Report: Redacted


Redacted	
	ı
	:
	:
	:



Standing on the line looking northwest



Standing on the line looking to the southeast



House, is within the easement area by 1.4'.

Final Report: Redacted

Redacted	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Santa Clara
Depth of Cover	40"
Pipeline:	132
Encroachment Type:	Garages


Summary:

There are two garages that fall within the easement on 132 at .9' and .6', but are not over the pipeline. One garage falls into the easement on 109 at .8', but is not over the pipeline.

Report of Findings for Line 132

Gas Pipeline Encroachment Pilot Program
Final Report: Redacted


edacted		
/		
5		




Standing on Line 132 looking to the east down the line.




Standing on Line 132 looking to the west up the line



Standing on Line 109 looking to the west up the line.



Parking Garage within the easement area.



Occupied Structure behind the vehicle.

Final Report: Redacted

Redacted	
1,1553,555	

Owner:	Redacted	
Property:	Redacted	
APN:	Redacted	
County:	Santa Clara	
Depth of Cover	th of Cover 40"	
Pipeline:	132	
Encroachment Type:	Concrete patio	

Summary:

Concrete patio is over the pipeline. House is not within the easement.

Final Report: Redacted

Re	dacted	
2		
1		
ш_		

Final Report: Redacted



Standing on the line looking northwest




Standing on line looking southeast

Final Report: Redacted



Standing on the line looking northwest



House is not within the easement area.