

Land & Environmental Management

Encroachment Pilot Report of Findings

	Gas Transmission Line 153 Encroachment Pilot Projects		
SAMPLE CONTRACTOR CONT	Redacted	Montagement on the Control of the Control	-
		Service Commonweal Common	
			_
		211001000000000000000000000000000000000	
		000000000000000000000000000000000000000	
			THE REAL PROPERTY AND ADDRESS OF THE PERSON NAMED IN COLUMN TWO IS NOT THE PERSON NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN COLUMN TWO IS NAMED IN THE PERSON NAMED IN
		ADMINISTRATION OF THE PROPERTY	The second secon
			CONTRACTOR DESCRIPTION OF THE PERSONS ASSESSMENT OF THE PERSONS ASSESS
ANTONIO DE COMPONIO DE COMPONI		Surpane and a su	Annual Company of the Parket
		WARRANCE CONTRACTOR OF THE PARTY OF T	Annual Company of the Parket Street, S
		The contract of the contract o	National Control of Co

Final Report: Redacted


edacted	


Owner:	Redacted	
Property:	Redacted	
APN:	Redacted	
County:	Alameda	
Depth of Cover	f Cover Loading Dock 15"	
	Building 50"	
Pipeline:	153	
Encroachment Type:	Building and 2 docks	

Summary:

This property has two major issues:

- 1. A portion of a storage area is directly over the gas line and within the easement area.
- 2. Loading docks for heavy trucks have been constructed over the gas line and within the easement. Cover over the gas line has been reduced to approximately 15 inches.






Standing on the line looking north.



Standing on the line looking to the south.



Building is over the easement.




Report of Findings for Line 153 Gas Pipeline Encroachment Pilot Program Final Report: Redacted

Redacted		

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Alameda
Depth of Cover	64"
Pipeline:	153
Encroachment Type:	Building

Summary:	
Redacted	building is entirely across PG&E's easement and over the pipeline across th
entire parcel.	





Standing on the line looking northeast.



Standing on the line looking southwest.



Building is over the line.



View inside the industrial shed over the line.


Final Report: Redacted

Redacted				
	Owner:	Redacted		

Owner:	Redacted
Property:	Redacted ,
APN:	Redacted
County:	Alameda
Depth of Cover	44"
Pipeline:	153
Encroachment Type:	Sheds and possible occupied structure

Summary:

There is two-story temporary living quarters that encroaches 6.47' in to the easement but is not over the pipeline. (These quarters are not occupied at this time, but have electrical service and appear to have been occupied for a time). There is an elevated wood structure (Tree House) that is within the easement and over the pipeline. There are two storage sheds (one wood, one metal) within the easement but not over the pipeline. The pool deck also encroaches slightly into the easement area; however we cannot tell if the pool shell itself is impacting the easement.





Standing on the line looking northwest.



Standing on the line looking to the northwest.



Standing on the line looking to the southeast.




Shed within the easement area.

Report of Findings for Line 153 Gas Pipeline Encroachment Pilot Program Final Report: Redacted



Tree house over the top of the line.



Pool deck within the easement area.



House within the easement area.



Shed within the easement area.

Redacted Redacted

Concrete slab and RV within the easement area.

Final Report:	Redacted


Redacted			

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Alameda
Depth of Cover	50"
Pipeline:	153
Encroachment Type:	Playhouse

Summary:

Wood Structure Playhouse is located on top of the pipe and is within the easement.

Final Report: Redacted



Report of Findings for Line 153 Gas Pipeline <u>Encroachment Pilot Program</u> Final Report:



Standing on the line looking southeast.



Playhouse is over the top of the line.


Final Report:	Redacted

Redacted	
I and the second	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Alameda
Depth of Cover	36"
Pipeline:	153
Encroachment Type:	Industrial shed

Summary:

Industrial shed is located on top of the existing gas line and is within the gas line easement and also appears to be located within an Electric Transmission easement. Storage containers with attached roof structure are located within the two easements. Miscellaneous storage racks are located within easements.






Standing on the line looking west southwest



Standing on the line looking east southeast



Standing on the line looking west southwest



Standing on the line looking east southeast

Final Report: Redacted



Standing on the line looking west southwest at the only non-removable structure an old shed


Final Report:	Redacted

Redacted	

Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Alameda
Depth of Cover	57"
Pipeline:	153
Encroachment Type:	House, Shed and Garage

Summary:

Corner of garage extension encroaches 1.43' into easement. Storage shed is completely within the easement and is over the pipeline. There is a concrete walkway within the easement and over a portion of the pipeline.



Final Report: Redacted



Standing on the line looking southeast.



Standing on the line looking to the northwest. Shed is over the top of the line.

Report of Findings for Line 153 Gas Pipeline Encroachment Pilot Program Final Report: Redacted



1.43' of the house is within the easement area.

Final Report:	Redacted	

dacted	


Owner:	Redacted
Property:	Redacted
APN:	Redacted
County:	Alameda
Depth of Cover	60"
Pipeline:	153
Encroachment Type:	Building

Summary:


Main building is very close to easement line but is not within the easement. Wooden deck and staircase are within the easement.

Report of Findings for Line 153


Gas Pipeline Encroachment Pilot Program




Final Report: Redacted



Standing on the line looking east northeast



Standing on the line looking east northeast at major encroachment which is an abandoned office building




Standing to the right of the line looking southwest through the office building




Standing on the line behind the building looking southwest there is a deck on the left

Final Report: Redacted




Standing behind the line looking at a cherry blossom tree that is possibly growing on top of the line



Standing on the line looking southwest



Standing behind the line looking at a permanent structure



Standing on the line looking at the first shed



Standing behind the line looking at the shed