	Pacific Gas and Electric Company
111111111111111111111111111111111111111	

## Leak Repair, Inspection and Gas Quarterly Incident Report (Form "A")

62-4060 TD-4110P-11-F01

Form Type \times Leak Compliance Due Date Assigned to Construction
Compliance Due Date Assigned to Construction Assigned to Work and Resource
District - Year - Series - Suffix Month - Day - Year
Leak Number 24-11-10537-1 USA Ticket # Valid Date
Location: B A = Above Ground B = Below Ground PCC Number 01860
Date Reported 10 - 07 - 2011 Time Reported 12:20 (24 hr Time) Paved Wall To Wall () Yes No
Response Date Response Time (24 hr Time) SAP Repair Order #
Gas Flow Stopped Date Stopped Time (24 hr Time)
Address: Warm Springs Blvd City: Fremont
Description of Reading Location: Over DFM by reg station large bell hole
Description of Housing Louising
Reported By: Call In
READINGS Grading Reason Via Vent DATE TIME OPERATOR NUMBER LOCATION REMARKS  SGAS Instruct Grading Code (b) (Yes/No) (24 hr Time) LANID (Lest 4 Diole)
(Not needed, if the same as previous)
0.5 C 3 10 - 07 - 2011 12:20 Redac 9314 Over DFM large bell hole front of reg st
GRADE 2+ REQUESTED REPAIR DATE (Only needed it less than 90 days)  Instrument Type Used to Grade: Enter, C for Combustible Gas Indicator, V for Visual  Enter Grade (1, 2+, 2, or 3). Enter 0 (zero) if no leak is found.  Grading reason code is required if leak is graded as 1, 2+, or 2 and/or is less than 2% gas:  A - Wall to wall and/or Continuously Paved, B - Near to, at, Inside or under building, C - Odor and next to public gathering location, D - In foreign structure,  E - Audible and/or visible, E - On facility in extremely poor condition, C - At least second customer call out, H - Leak is reported as 0% Gas Visual,  L - Leak Within the scope of work by others, M - Migration, N - Grade 3 downgrade is not allowed.  MAPPING DATA  (Repair required within 90 catendar days)  (Repair required within 90 catendar days)  (Repair required within 90 catendar days)  (Repair required within 90 catendar days)
Location Map Wall Map:27
Location Map Wall Map:27
For Leaks On Services: Main Connected to Service ( ) Cast Iron ( ) Plastic ( ) Steel Installation Year of Main
HIGH CONSEQUENCE AREA
High Consequence Area
Is leak source responsible for HCA? Yes No (Yes if dia & press produce impact circle creating HCA)
Is leak source a mechanical joint which can be repaired by tightening? Yes No (if no, normal leak grading and response applies

Date Printed: 05 July 2012