

Photo of tram prior to modifications made post-accident



Note: The Caution sign in the upper right corner was installed post-accident

Photo of tram with modifications made post-accident

