

From: [Redacted]
Sent: 2/12/2014 3:46:25 PM
To: Lok, Ronald E. (ronald.lok@cpuc.ca.gov)
Cc: [Redacted] [Redacted] Halpin, Ed
(/O=PG&E/OU=Corporate/cn=Recipients/cn=EIH8); Beck, Valerie
(valerie.beck@cpuc.ca.gov); Tse, Rick (rick.tse@cpuc.ca.gov); Jacobson, Erik B
(RegRel) (/O=PG&E/OU=Corporate/cn=Recipients/cn=EBJ1); [Redacted]
[Redacted]
Bcc:
Subject: RE: Data Response: DCP Unit 2 Forced Outage

Good Afternoon Ron,

Please see the attached documents in response to your request for data.

- 1) Licensee Event Report 2-2013-005-01, "Unit 2 Reactor Trip due to Lightning Arrester Flashover" DCL-13-112_Attch_01.pdf
- 2) NRC INTEGRATED INSPECTION REPORT 05000275/2013005 and 05000323/2013005
ML14043A056_Attch_02.pdf

Kind Regards,

[Redacted]

Energy Supply Regulatory Compliance and Support, Pacific Gas and Electric Company
Mailing address: 245 Market Street, Mail Code N13X, Office 1376, San Francisco, CA, 94105

[Redacted]

From: Lok, Ronald E. [mailto:ronald.lok@cpuc.ca.gov]
Sent: Tuesday, February 11, 2014 2:26 PM
To: [Redacted]

Cc: Tse, Rick; Beck, Valerie; Haipin, Ed; [Redacted] Jacobson, Erik B (RegRel)
Subject: RE: Data Response: DCP Unit 2 Forced Outage

Lisa,

Thank you for your response. Also, please submit the investigation report that was submitted to the NRC for the DCP Unit 2 flash over incident (“A” phase lightning arrester) on July 10, 2013; and the NRC response, did the NRC issue a violation for this incident?

Thanks,

Ron Lok

CPUC