
## **Cross Bores Inspections**


#### **Distribution Integrity Management**

May, 2014









2002: Minneapolis MinnesotaFire, explosion and two homes destroyed 2008: Cross Bore Safety Association formed, a non-profit organization of construction, pipe manufacturer, inspectors and utility professionals

- Eighteen known cross bore incidents in U.S. since 2002<sup>1</sup>
- Industry average cross bores estimated at 2-3 per mile of gas pipe and can be higher regionally, especially if sewer and gas lines are installed at the same depth<sup>2</sup>
- Incident in Minnesota resulted in a state mandated program to address cross bores<sup>3</sup>

<sup>1</sup>GTI "Mitigating the Risk of Cross-Bores", presentation to Northeast Gas Association, October 4, 2012

<sup>2</sup> Cross Bore Safety Association (CBSA), Legacy Cross Bores


<sup>3</sup> Minnesota Department of Public Safety, State Fire Marshal and Pipeline Safety, Alert Notice, May 10, 2010

2012: Gas Technology Institute (GTI) publishes report on Cross-Bores Best Practice and Outreach Program

Best practices focus on:

 Compliance, resources, awareness, records and risk assessment and mitigation


### PFGE PG&E's History with Cross Bores



# PF&F PG&E's Cross Bore Safety Program

#### Legacy Inspections


- Camera inspections of sewer mains and laterals to locate potential legacy cross bores
- Risk-based prioritization of inspections based on public assembly locations and population density (e.g., schools, hospitals)
- Inspections focused on known locations of boring technology use
- Rigorous tracking of inspected parcels





#### Camera equipment is either


- Inserted into a sewer manhole and launched up each individual sewer lateral
- Inserted through a toilet, trap, or cleanout at the house and pushed to the street








### **PGGE Tracking, Notification and Repair Process**




When a cross bore is identified:

- Owner of sewer notified
- PG&E crews dispatched if blockage condition exists
- Gas line relocated out of sewer lateral
- Sewer repaired by licensed plumber
- Find rate is approximately 1 per 1,000 inspections or roughly 2 per mile of main, consistent with industry experience




### <sup>°</sup>Outreach and Education

- Materials distributed to key stakeholders explaining cross bores and requesting appropriate action when a cross bore is suspected.
- In 2012, PG&E sent safety brochures on Cross Bores to 12,500 sewer districts, public works agencies, plumbers, and equipment rental stores.
- In 2013, we completed two notifications totaling 25,000 brochures with an additional 283 mailings to sewer agencies and plumber unions.
- In 2014, in addition to our stakeholder mailings, we included cross bore information in March as a bill insert.



# **Cross Bore Prevention Process**



\*Perform before job closeout if pre-locate was completed. Perform within 24 hours if NO pre-locate was completed. 9



Program	Benchmark Source	Comments
Legacy	American Gas Association Survey	PG&E provides public outreach consistent with the industry best practices.
		Not all utilities have legacy inspection programs.
	American Gas Association Survey	PG&E's new procedures implements best practices to ensure crossbores are not created given the combination of the pre-camera, pothole and post- camera inspections.
	Gas Technology Institute (GTI)	
	Local and National Contractors	
Prevention		
	Other Major US Utilities	PG&E is not only consistent with practices followed by other major US utilities but also meets best practices outlined in GTI's "Cross Bore Best Practices – Best Practices Guide".