

Aspen
Environmental Group

Figure 2.2-79

Grouted Rock West Crossing (Typical Installation)