



KOP-South-12 was established within a residential neighborhood in the western portion of the landscape unit on Crooked Creek Drive, less than ¼ miles northeast of KOP-South-11, looking south-southeast at the existing transmission line corridor.

Overall Visual Sensitivity: high. For residents of Crooked Creek Drive in general and KOP-South-12 specifically, the ratings of high viewer exposure, high viewer concern, and moderate-to-high visual quality lead to a high overall visual sensitivity of the visual setting and viewing characteristics.

Figure A-47a
Existing Conditions
for KOP-South-12
Crooked Creek Drive,
Diamond Bar
(Alternative 2, Segment 8)

Source: SCE, 2007.