

Source: SCE, 2006.

PREPARED BY Aspen Environmental Group

Figure B.1-4
SCE Rector System within Electrical Needs Area