
Approximate Location of the Leak
17-000
17-000
HILLMONT
McCORMICK
SUNKIST
MICHIGAN
UTAH ST.
FOUNTAINE
ELMONT
THERMAL
SENECA
MALVINGSOON
GOLF LINKS
HILLMONT
CHESTNUT
PARKER
McARTHUR
IRIS
SHONE
CREST
AVE.
BLVD.
ST.
RD.
DR.

Leak Survey and Field Inspections Stamp

Wall Map/Plat: 103-3 Previous Leak Survey Start Date: 3-9-07

Scheduled Month/Year: 3-12 Previous Leak Survey Complete Date: 3-19-07

Survey Frequency/Type: ☒ 5-Year Survey ☐ 3-Year Survey ☐ Annual Survey ☐ 6-Months Survey ☐ Special Survey ☐ Audit

Address/Location Description: Town/City:

Date Surveyed	Surveyor LAN ID	Sample Color Highlighter Used	Type and Manufacturer Of Instrument Used[2]	Wind Speed Start of Day (MPH)[3]	Wind Speed Middle of Day (MPH)[3]	Serial Number Of Leak Survey Instrument (last 4 digits)	Foot Survey ☑	Mobile Survey ☑	Atmospheric Corrosion Survey ☑	Field Inspections Survey ☑	Actual Hours Surveyed[4]	Ft of Main Surveyed	# of Services Surveyed
4-5-12	J5C8	[redacted]	HR	4	10	3002	☑	☐	☐	☑	5.5	3571	96
4-9-12	SAVA	—	H.O	0	0	4006	☐	☑	☑	☑	2	5353	Ø
4-16-12	J5C8	[redacted]	HR	0	3	3002	☑	☐	☐	☑	7	7,304	125
4-18-12	J5C8	[redacted]	HR	0	5	3002	☑	☐	☐	☑	7	1,352	44
4-19-12	J5C8	[redacted]	HR	0	0	3002	☑	☐	☐	☑	4	5264	49
5-7-12	J5C8	[redacted]	HI	2	5	3002	☑	☐	☐	☑	7	8,276	109
5-8-12	J5C8	[redacted]	HI	0	2	6009	☑	☐	☐	☑	4	1128	40
5-9-12	J5C8	[redacted]	IR	0	5	4010	☑	☐	☐	☑	4	2425	68
5-10-12	J5C8	[redacted]	IR	0	2	4010	☑	☐	☐	☑	5	2006	54
5-11-12	J5C8	[redacted]	IR	0	—	4010	☑	☐	☐	☑	2	620	23
5-22-12	J5C8	—	HI	0	0	3002	☑	☐	☑	☑	5	0	26
5-23-12	J5C8	—	HI	0	0	3002	☑	☐	☑	☑	3	0	11
							☐	☐	☐	☐		