



Sierra Pacific™

[www.sierrapacific.com](http://www.sierrapacific.com)

6100 Neil Road, P.O. Box 10100, Reno, Nevada 89520-0024 • 775.834.4011

---

July 31, 2006

Colleen Sullivan  
California Public Utilities Commission  
505 Van Ness Avenue  
San Francisco, CA 94102

Dear Ms. Sullivan:

Attached is a copy of the Annual GO 165 Report for Sierra Pacific Power Company. This report is submitted in compliance with Section III of GO 165. We sincerely apologize that this report was not sent to you on July 1, 2006, and will endeavor to file it timely in the future.

If additional information is required, please do not hesitate to call me at (775) 834-4686.

Sincerely,

Debbie Rice  
Rates Analyst

**TAHOE DISTRICT ANNUAL GO 165 REPORT**  
**YEAR 2005**

**YEAR 2006**

All Inspected Circuits	Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% of Total Units for Repair	# of Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired	% of Units Repaired
<b>Transformers</b>									
Overhead	196	196	33	16.8 %	0	0	0	0	0
Underground	0								
Padmounted	0								
<b>Switching/Protective Devices</b>									
Overhead	358	358	0	0	0	0	0	0	0
Underground	0								
Padmounted	0								
<b>Regs./Capacitors</b>									
Overhead	0								
Underground	0								
Padmounted	0								
<b>Distribution Conductors &amp; Cable Miles</b>	25 mi.								
<b>Pole Line Hardware, Infractions, Etc.</b>									
	839	839	273	32.5%	123	45%	45	0	0
<b>Vaults, Boxes &amp; Manholes</b>									
	0								
<b>Junction Enclosures</b>									
	0								
<b>Wood Poles</b>									
Wood Poles Inspected	839	839	0	0	0	0	0	0	0
Wood Poles Intrusively Inspected	1773	1773	102	5.7%	102	100%	0	0	0