www.sierrapacific.com

6100 Neil Road, P.O. Box 10100, Reno, Nevada 89520-0024 • 775.834.4011

July 2, 2007

Colleen Sullivan California Public Utilities Commission 505 Van Ness Avenue San Francisco, CA 94102

Dear Ms. Sullivan:

Attached is a copy of the Annual GO 165 Report for Sierra Pacific Power Company. This report is submitted in compliance with Section III of GO 165.

If additional information is required, please do not hesitate to call me at (775) 834-4686.

Sincerely,

Debbie Rice

Case Manager

Rates and Regulatory Affairs

Mobile Rice

Attachment

TAHOE DISTRICT ANNUAL GO 165 REPORT YEAR 2006

	_
i	-
i	-
	×
	\sim
7	≡
•	-1

		0	0	0	0	0	216	216	Wood Poles Intrusively Inspected
		0	0	0	0	0	7428	7428	Wood Poles Inspected
									Wood Poles
		9	0%	0	9%	6	64	64	Junction Enclosures
		17	0%	0	10%	17	176	176	Vaults, Boxes & Manholes
		1597	8%	148	23%	1745	7428	7428	Pole Line Hardware, Infractions, Etc.
							378 mi.	378 mi.	Distribution Conductors & Cable Miles
		0	0	0	0	0	0	0	Padmounted
		0	0	0	.0	0	0	0	Underground
		0	. 0	0	0	0	22	22	Overhead
									Regs./Capacitors
				- 					
		1	0%	0	%6	1	11	11	Padmounted
		0	0	0	0	0	1	þi-vá	Underground
		127	0%	0	18%	127	705	705	Overhead
									Switching/Protective Devices
				į					2000
		12	8%	1	4%	13	329	329	Padmounted
		3	%0	0	2%	3	132	132	Underground
		178	1%	2	17%	180	1087	7801	Overhead
									Transformers
-									
% of Units Repaired	# of Units Repaired	Units Scheduled for Repair	% of Units Repaired	# of Units Repaired	% of Total Units for Repair	# of Units for Repair	Total Units Inspected	Units Scheduled for Inspection	All Inspected Circuits