



California Pacific Electric Company, LLC
933 Eloise Avenue
South Lake Tahoe, CA 96150
Telephone: 1-800-782-2506
Fax: 530-544-4811

July 1, 2013

Mr. David Lee
Utility Engineer
California Public Utilities Commission
505 Van Ness Avenue
San Francisco, CA 94102

Re: **California Pacific Electric Company, LLC (U 933-E) General Order 165 Filing for 2013**

Dear Mr. Lee:

Pursuant to Section III.D of General Order 165, please find the 2013 report of California Pacific Electric Company, LLC (U 933-E) regarding its 2012 inspections.

If additional information is required, please do not hesitate to call me at (530) 543-5277.

Regards,

Michael D. Long

Director of Finance and Manager of Regulatory Affairs

California Pacific Electric Company, LLC (U 933-E)
ANNUAL GO 165 REPORT

Year - 2012

Year - 2013

	<i>E</i>	<i>F</i>	<i>G</i>	<i>H</i>	<i>I</i>	<i>J</i>	<i>L</i>	<i>M</i>	<i>N</i>
All Inspected Circuits	<i>Units Scheduled for Inspection</i>	<i>Total Units Inspected</i>	<i># of Units Scheduled for Repair</i>	<i>% of Total Units Scheduled for Repair</i> <small>(Column G/F)</small>	<i># of Units Scheduled for Repair - Repaired</i>	<i>% of Units Repaired</i> <small>(Column I/G)</small>	<i>Units Scheduled for Repair</i>	<i># of Units Repaired to Date</i>	<i>% of Units Scheduled for Repair - Repaired to Date</i> <small>(Column M/L)</small>
Transformers									
Overhead	493	493	133	27.0%	0	0.0%	133	0	0.0%
Underground	132	132	39	29.5%	8	20.5%	31	0	0.0%
Padmounted	379	379	77	20.3%	111	144.2%	0	70	0.0%
Switching / Protective Devices									
Overhead	106	106	17	16.0%	0	0.0%	17	0	0.0%
Underground	0	0	0	0.0%	0	0.0%	0	0	0.0%
Padmounted	23	23	10	43.5%	7	70.0%	3	2	66.7%
Regulators / Capacitors / Reclosures									
Overhead	2	2	0	0.0%	0	0.0%	0	0	0.0%
Underground	0	0	0	0.0%	0	0.0%	0	0	0.0%
Padmounted	0	0	0	0.0%	0	0.0%	0	0	0.0%
Distribution Conductors & Cable Miles	129.94	129.94	~	~	~	~	~	~	~
Pole Line Hardware, Infractions, etc.	3100	3100	806	26.0%	1024	127.0%	0	225	0.0%
Vaults, Boxes & Manholes	0	0	0	0.0%	10	0.0%	0	0	0.0%
Junction Enclosures	121	121	12	9.9%	57	475.0%	0	4	0.0%
Wood Poles									
Wood Poles Inspected	3100	3100	~	~	~	~	~	~	~
Wood Poles Intrusively Inspected	2445	2445	~	~	~	~	~	~	~

Note: The "# of Units Scheduled for Repair" and the "% of Units Repaired" includes work that was completed in arrears.