

From: Cooke, Michelle  
Sent: 4/15/2011 8:49:54 AM  
To: Horner, Trina (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=TNHC)  
Cc:  
Bcc:  
Subject: Weld Question from one of our engineers

1. Last night while reviewing API's Recommended Practice 11110 Fifth Edition, June 2007 it became clear that there is a potential problem contained within PG&E's Hydrotest Program.

2. THE PROBLEM: Because of the way PG&E has proposed to establish the test boundaries for each segment by cutting the pipe and capping in lieu of using valve closures, internal plugs/dams, or freeze plugs the four (4) new welded joints will not easily be hydrotested as required by CFR 49 Part 192.

We would like PG&E's response to this potential problem.

**Michelle Cooke**

Assistant Chief Administrative Law Judge

415 703 2637

[mlc@cpuc.ca.gov](mailto:mlc@cpuc.ca.gov)

