

**PACIFIC GAS AND ELECTRIC COMPANY  
San Bruno GT Line Rupture Investigation  
Data Response**

PG&E Data Request No.:	CPUC_096-03		
PG&E File Name:	SanBrunoGT-LineRuptureInvestigation_DR_CPUC_096-Q03		
Request Date:	March 8, 2011	Requester DR No.:	
Date Sent:	March 14, 2011	Requesting Party:	CPUC (CPSD)
		Requester:	Michael Robertson

**QUESTION 3**

Subsequent to 1993, how were the remaining welds on Line 132 determined to be in satisfactory condition?

**ANSWER 3**

The Gas Pipeline Replacement Program was designed to identify and mitigate possible pipe joint problems (e.g., oxyacetylene gas welds). PG&E had no reason to suspect the girth welds on this segment of Line 132 because all the girth joints were welded with a shielded metal arc welding process.