

**PACIFIC GAS AND ELECTRIC COMPANY
San Bruno GT Line Rupture Investigation
Data Response**

PG&E Data Request No.:	CPUC_096-04		
PG&E File Name:	SanBrunoGT-LineRuptureInvestigation_DR_CPUC_096-Q04		
Request Date:	March 8, 2011	Requester DR No.:	
Date Sent:	March 14, 2011	Requesting Party:	CPUC (CPSD)
		Requester:	Michael Robertson

QUESTION 4

To our understanding, both north and south of the segment that failed in San Bruno were replaced. Is this correct?

ANSWER 4

Yes, there were sections of pipe replaced approximately one-tenth of a mile to the north and one-third of a mile to the south of the rupture site.