

From: Ramaiya, Shilpa R  
Sent: 9/16/2011 3:58:26 PM  
To: 'Cooke, Michelle' (michelle.cooke@cpuc.ca.gov) (michelle.cooke@cpuc.ca.gov)  
Cc: Horner, Trina (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=TNHC);  
Dowdell, Jennifer (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=JKD5)  
Bcc:  
Subject: San Carlos Hydrotesting  
Michelle,

Jennifer passed on your message regarding the delay in the San Carlos hydrotesting schedule. Here's what I learned about the cause:

There was erosion discovered stemming from high flow/rain at the San Francisquito Creek in the middle of the Stanford Golf Course. As a result, Line 109 will need to be repaired immediately before the winter. With this unplanned work on Line 109 which will result in some shut-in and lowering of pressure on the line, the test in San Carlos cannot proceed until this work is done.

On a separate but related note, our T-29 hydrotest on Line 109 also ran long because there was mercury in the line that needed to be washed away several times and a pig got stuck.

If the Creek work and T-29 are completed as scheduled, we expect that the San Carlos hydrotesting will begin Sept 30/Oct 1 and be complete by Oct 18.

Thanks.

Shilpa

415-973-3186