

From: Cooke, Michelle
Sent: 10/24/2011 12:11:08 PM
To: Shori, Sunil (sunil.shori@cpuc.ca.gov); Halligan, Julie (julie.halligan@cpuc.ca.gov); Dowdell, Jennifer (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=JKD5)
Cc: Doll, Laura (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=LRDD); Horner, Trina (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=TNHC); Ramaiya, Shilpa R (/o=PG&E/ou=Corporate/cn=Recipients/cn=SRRd)
Bcc:
Subject: RE: failure notification

Thank you. We've gotten the notification and Shilpa and Larry are on it for getting us the info we have requested.

Michelle

-----Original Message-----

From: Dowdell, Jennifer [mailto:JKD5@pge.com]
Sent: Monday, October 24, 2011 12:07 PM
To: Cooke, Michelle; Halligan, Julie; Shori, Sunil
Cc: Horner, Trina; Ramaiya, Shilpa R; Doll, Laura
Subject:

Michelle, Julie, and Sunil,

I know you've seen the pressure test failure report that was submitted to the CPUC this morning on L300B in a rural area.

Shilpa is following up. Not sure if you have all info below yet.

Hope this helps

Jennifer

Basic info on failed line is as follows:

- 34 inch line
- DSAW
- 757 MAOP
- Class 1
- Failed at 998 psig, or 131.8% of MAOP or 94.9% SMYS

Additional Background:

Line 300B failed a pressure test this morning. The location of the failure was in an agricultural field near Rosedale. It appears that the

pipe failed along a longitudinal seam during the ramp portion of the test. A team is en route to further evaluate the failure.