

From: Ramaiya, Shilpa R  
Sent: 11/6/2011 5:12:59 PM  
To: michelle.cooke@cpuc.ca.gov (michelle.cooke@cpuc.ca.gov);  
julie.halligan@cpuc.ca.gov (julie.halligan@cpuc.ca.gov); sunil.shori@cpuc.ca.gov  
(sunil.shori@cpuc.ca.gov)  
Cc: Doll, Laura (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=LRDD);  
Horner, Trina (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=TNHC);  
Dowdell, Jennifer (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=JKD5)  
Bcc:  
Subject: Line 132 Hydrotest Failure

Michelle, Julie, Sunil,

I just learned of a hydrotest failure on T-31 that caused mud from the rupture to shut down part of Highway 280. No accidents and no injuries. It was at the corner of Redacted And the pressure when it ruptured was above 500 psi.

More details to come. Quang Pham of the CPUC was informed as he was observing T-30.

3 of 4 highway lanes are now open.

Shilpa