

From: [Redacted]
Sent: 7/6/2012 12:13:59 PM
To: 'Shori, Sunil' (SKS@cpuc.ca.gov)
Cc: Ramaiya, Shilpa R (/o=PG&E/ou=Corporate/cn=Recipients/cn=SRRd)[Redacted]
[Redacted]
Bcc:
Subject: FW: PR-002 leak in street pics.

-----Original Message-----

From: [Redacted]
Sent: Friday, July 06, 2012 11:38 AM
To: Campbell, Ben (Hydrotest); [Redacted]
Cc: [Redacted] Mannie, Joel C; [Redacted] [Redacted]
Subject: RE: PR-002 leak in street pics.

Ben [Redac]
Here's the pics of the corrosion leak on PR00-2. Pinhole.

[Redacted]
GC Field Engineer
Pipeline Safety Enhancement
PG&E [Redacted]

-----Original Message-----

From: Campbell, Ben (Hydrotest)
Sent: Thursday, July 05, 2012 9:09 AM
To: [Redacted]
Cc: [Redacted]
Subject: RE: PR-002 leak in street.

[Redacted]

Do you want us to get a picture of the cutout section from Modesto?

Ben

-----Original Message-----

From: [Redacted]
Sent: Thursday, July 05, 2012 9:06 AM
To: Campbell, Ben (Hydrotest)
Subject: Re: PR-002 leak in street.

I never got a close up. But I'll ask around. The piece is in Modesto. I'm sure I can get one.

----- Original Message -----

From: Campbell, Ben (Hydrotest)
Sent: Thursday, July 05, 2012 08:56 AM

To: [Redacted]
Cc: [Redacted]
Subject: RE: PR-002 leak in street.

[Redacted]

Did anyone take pictures of this leak when it was dug up where you can see the damage? If so, can you shoot me a couple of the pictures?

Ben

-----Original Message-----

From: [Redacted]
Sent: Thursday, April 19, 2012 9:08 AM
To: Campbell, Ben (Hydrotest)
Cc: [Redacted] Cabral, Mark; Moreland, Chauna; Mannie, Joel C.; [Redacted] [Redacted]
[Redacted]
Subject: PR-002 leak in street.

Ben,
Pictures of Warm Springs Blvd. After I soaped the cracks in the street. We are currently pin pointing where to dig. I spoke with the city inspector and he understands our situation.

[Redacted]
GC Field Engineer
Pipeline Safety Enhancement
PG&E [Redacted]