From:	Doll, Laura
Sent:	10/7/2013 4:51:08 PM
То:	Malashenko, Elizaveta I. (elizaveta.malashenko@cpuc.ca.gov); Redacted (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=Redact)
Cc:	Gas Ops Support (/O=PG&E/OU=Corporate/cn=Recipients/cn=SBResponderGroup)
Bcc:	
Subject:	RE: Antioch Project Incident
Liza	
you have sp	swers to your 9/11/13 question about an event on the Antioch Project during construction. I believe token further with Redacted about this as well. We consider these answers to close out the I know you'll let us know if you need further information.
Thanks	
Laura	
QUESTION	J:
4266.01 Please validate the account provided above and provide me with a detailed statement of what happened on the line 281 project.	
RESPONSE: Observations described above refer to PSEP Strength Test T-281B-13 on Line 191. On 9/10/13 at Location B on Century Blvd., a representative of Bureau Veritas (BV), Modena Moore, was observed taking pictures of the work site. The site safety representative orally reviewed the site Job Safety Analysis (JSA) with the BV representative, requested the representative to keep 10 feet back from all active work areas, and sign in on the JSA. Following this discussion, the site safety representative later observed the BV representative interrupting the welding crew, asking questions, and taking pictures within 3 feet of active welding activities.	
site without approached containing of sign the site returned to	at Location C on Mahogany Blvd., the same BV representative was again observed accessing the work first checking in, reviewing site safety hazards, or signing the site specific JSA. Prior to being by the site safety representative, the BV representative was observed entering a barricaded area drug needles and leaning over an exposed excavation to take pictures. When requested to review and especific JSA, the BV representative became upset. After leaving this location, the BV representative Location B and again did not check in or sign the site-specific JSA prior to accessing the work site, ain disregarded the requested 10 feet buffer around active work areas.
QUESTION 4266.02 PI JSA KEVIN	lease send me a copy of the PG&E procedure that outlines the requirement for everyone to sign the
	E: Per Redacted email and phone call on 10/4/2013, this request can be closed out. Reda ended to Liza.
	l Message shenko, Elizaveta I. [mailto:elizaveta.malashenko@cpuc.ca.gov]

Sent: Wednesday, September 11, 2013 3:55 PM
To: Redacted; Doll, Laura
Subject: RE: Antioch Project Incident
Thank you! I just realized I got the name wrong - the person who called was BILL, not Brian and Bill's number is Redacted just to make it easier for you to figure out who I'm talking about.
Elizaveta Malashenko
Deputy Director
Office of Utility Safety and Reliability Safety and Enforcement Division California Public Utilities Commission
Phone: 415-703-2274
E-mail: elizaveta.malashenko@cpuc.ca.gov
Original Message
From: Redacted
Sent: Wednesday, September 11, 2013 3:45 PM
Го: Malashenko, Elizaveta I.; Doll, Laura
Subject: RE: Antioch Project Incident
Liza,
Thanks for the email we will follow up as requested.
Regards
Redacted
Original message
From: "Malashenko, Elizaveta I." <elizaveta.malashenko@cpuc.ca.gov></elizaveta.malashenko@cpuc.ca.gov>
Date:
To: "McDonagh, Colin" <c1ms@pge.com>,"Doll, Laura" <lrdd@pge.com></lrdd@pge.com></c1ms@pge.com>
Subject: Antioch Project Incident

Colin and Laura,

Earlier today, CPUC received a phone call from Brian, a PG&E construction manager on the PSEP program. I just called Brian back (sorry, didn't get his last name) and spoke with him about an incident that concerns him.

From what I understood from Brian, PG&E construction staff on the Antioch hydrotesting project (line 281) are concerned with something that happened recently involving a CPUC contractor. Specifically, apparently a BV employee (Modena Moore) was taking pictures of welding being performed. The safety procedure is that there is a

10 foot "safety zone" established when welding is taking place. Modena was inside the "safety zone" and getting very close to the weld. She was asked by PG&E staff to step back, but apparently was not cooperative. Apparently, PG&E employees also asked her to sign the Job Safety Analysis (JSA) worksheet, but again Mondena supposedly was not cooperative. From what I understand, everybody on a job site is supposed to sign the JSA when they arrive and review the pertinent safety information.

My request is the following:

- (1) Please validate the account provided above and provide me with a detailed statement of what happened on the line 281 project.
- (2) Please send me a copy of the PG&E procedure that outlines the requirement for everyone to sign the JSA

Thanks!

Liza

Elizaveta Malashenko

Liizaveta iviaiasiici.

Deputy Director

Office of Utility Safety and Reliability Safety and Enforcement Division California Public Utilities Commission

Phone: 415-703-2274

E-mail: elizaveta.malashenko@cpuc.ca.gov

PG&E is committed to protecting our customers' privacy.

To learn more, please visit http://www.pge.com/about/company/privacy/customer/