Redacted						
_						
From:	Redacted,))	. 7			
Sent:		October 22, 201;			Dodostod	
To:	Redacted Redacted		Redacted	Redacted	Redacted	.); Redacted
			1.4	Redacted	7	
Cc:	Redacted	<u>; Mannie, Joe</u>	edacted edacted	<u> </u>	Redacted	;Red Redacted
	Redacted	1:170		; Redacted	Redacted	1 readacted
	Redacted		<u> </u>			
Subject:	RE: PM# 4	41756015: L-14	/ Leak Mi _{Red}	acted		
edacted						
When will the repa	air take place? I ma	y take a run out	there to take	a look for mysel	f.	
·	per our previous dis		e will be cut o	out at a convenie	nt later date to fo	r the purpose of
performing a full r	oot-cause investiga	tion.				
THANKS						
dacted						
Daire aire al Como e						
Principal Corros	~					
PG&E Pipeline	Corrosion Contro	ol				
NACE CP Spec	ialist Redacted					
NACE Internal	Carragion Toolan	Redacte	d			
NACE Internal (Corrosion Techno	ologistiricadec	<u> </u>			
ledacted						
D						
From Redacted						
Sent: Sunday, Oct	ober 21. 2012 6:11	PM			Redacted	
To: Redacted		Redacted	Redac	ted :		
	Mannie, Joel (Redact		,,	, , , ,		
<u> </u>	Tarriner Soci encade	Redacted			-	
edacted	2ECO4E. 447 1.				\neg	
Subject: PM# 417	756015: L-147 Leak	Redacted				
HiRedacted						
				45		
	e leak repair work c		ntersection c	Redacted		The PM# for
this repair is 41756	6015 (Repair Plan at	tached).				_ _
Redacted	and Redacted	would like a D	ina ta Sail Da	ad takon bafara t	he pipe is fully ex	cavated They
<u> </u>			•			•
would like	the top of the 20" p	pipe to be expos	sed, a small a	rea of coating ren	noved, and a CP re	ead taken while th
pipeline is	in its native environ	ment. I'd also l	ike to get son	ne photos of the I	eaking corrosion i	oit at 6 o'clock on
	മുല്ലോared for the slo		_		you would like d	
tile alea is	Reda .	Redacted	11 you 11	ave anything else	you would like u	one, piease iet
myself or l	Reda know.					
	0.375" 50,000 psi SN	MYS Type B Rep	air Sleeve is b	eing delivered to	Redacted	
	enter Yard) on Mond			-		
					J\ Tha \4!	Moldin - Du
	Procedure for instal	_		-		weiging Pressure
above the	current operating p	ressure of 285	osig, so no lo	wering is required	l.	
 The sleeve 	welds will need to	be X-rayed and	MT inspected	d.		
Redacted	will p				of the repair (cor	·
Redacted		The GC Welde	rs and Forem	an will need to sig	gn-off on this A-Fo	orm, and include a
	pe inspection and Cl	P information o	btained.			
1 1 1			1			
			1			

•	I've asked Redacte / Redacted to notify the city of San Carlos Public Works department so they are aware of					
	our activities in their roadway on Brittan Ave Redacted - Please let me or Reda know if there is a specific city					
	inspector or contact we should be notifying. The work is planned for Monday 10/22 WEATHER PERMITTING.					
	The forecasted rain may push our schedule out a couple of days.					

I'll be out on Monday, but back Tuesday 10/23 if you have any questions let me know. Thanks to all for your involvement in this repair effort.

Red .	
Redacted Redacted	