From: Yura, Jane

Sent: 12/16/2013 12:45:10 PM

To: Malashenko, Elizaveta I. (elizaveta.malashenko@cpuc.ca.gov)

(elizaveta.malashenko@cpuc.ca.gov)

Cc: Gibson, Bill (Codes) (/o=PG&E/ou=Corporate/cn=Recipients/cn=WLG3); Clanon,

Paul (paul.clanon@cpuc.ca.gov); ejh@cpuc.ca.gov (ejh@cpuc.ca.gov); Doll, Laura

(LRDD@pge.com) (/O=PG&E/OU=Corporate/cn=Recipients/cn=LRDD); Redacted

Redacted Thierry.

Raymond (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=RXT5)

Bcc:

Subject: 12/16/13 PG&E Oakland Incident - Update

Liza, the attached information provides an update on the 12/10/13 gas distribution system incident in Oakland, and the ongoing root cause analysis.

The investigation thus far, with the support of Exponent Engineering, indicates that the failure of the 4-inch steel elbow resulted from a single, significant external force to the pipeline. As one of our interim safety measures, PG&E plans to conduct a special leak survey of the area surrounding the failure to monitor for any leaks as we continue to perform the root cause analysis.

We will continue to provide updates as the analysis progresses.

Jane

From: Yura, Jane

Sent: Wednesday, December 11, 2013 5:40 PM

To: Malashenko, Elizaveta I. (elizaveta.malashenko@cpuc.ca.gov)

Cc: 'ejh@cpuc.ca.gov'; Clanon, Paul; Doll, Laura (LRDD@pge.com); Gibson, Bill (Codes): Redacted

Redacted Thierry, Raymond

Subject: PG&E Oakland Update

Liza, here is an update on the 12/10/13 gas incident on Golf Link Road in Oakland, including information on the previous gas leak survey, as well as the CPUC reportable incident form that was submitted earlier.

Please let me know if you need additional information, and we will keep you informed on the failure analysis of the pipe.
Jane
Jane Yura
PG&E Gas Operations
Asset & Risk Management
(415) 308-6985