

From: Doll, Laura
Sent: 1/7/2014 12:02:41 PM
To: pac@cpuc.ca.gov (pac@cpuc.ca.gov); eim@cpuc.ca.gov (eim@cpuc.ca.gov);
terrie.prosper@cpuc.ca.gov (terrie.prosper@cpuc.ca.gov)
Cc:
Bcc:
Subject: Fw: CPUC Reportable Gas Incident - Hayward Update

Fixed.

From: Redacted
Sent: Tuesday, January 07, 2014 11:25 AM
To: UO EP Gas Incident Notif
Cc: Redacted
Subject: RE: CPUC Reportable Gas Incident - Hayward Update

UPDATE:

The leak was found at the riser service valve, which was fixed by the crew. A leak survey was conducted in the area and no LEL values were detected. Gas service to Redacted was restored at approximately 0956 hours.

If you have any questions, please let me know.

Thanks,

Redacted

Regulatory Compliance

Gas Operations | Pacific Gas and Electric

6111 Bollinger Canyon Road, 4th Floor

San Ramon, CA 94583

Redacted

Redacted

From: Redacted

Sent: Tuesday, January 07, 2014 10:41 AM

To: UO EP Gas Incident Notify

Cc: Redacted

Subject: CPUC Reportable Gas Incident

On January 7, 2014, at approximately 0821 hours, the Hayward Fire Department reported a gas odor inside Redacted located at Redacted in Hayward. The Fire Department shut off the gas and the California Highway Patrol evacuated approximately 700 people from the building. A Pacific Gas and Electric (PG&E) gas service representative was onsite at 0840 hours. At approximately 0845 hours, when the gas odor dissipated, the evacuated people were let back into the building. A PG&E leak survey crew is en route to conduct a leak survey to investigate the cause and the source of the gas odor. Channel 7 News was on the scene at approximately 0840 hours, making this incident reportable to the CPUC.

Redacted

Regulatory Compliance

Gas Operations | Pacific Gas and Electric

6111 Bollinger Canyon Road, 4th Floor

San Ramon, CA 94583

Redacted