

From: Doll, Laura
Sent: 1/7/2014 12:02:41 PM
To: pac@cpuc.ca.gov (pac@cpuc.ca.gov); eim@cpuc.ca.gov (eim@cpuc.ca.gov);
terrie.prosper@cpuc.ca.gov (terrie.prosper@cpuc.ca.gov)
Cc:
Bcc:
Subject: Fw: CPUC Reportable Gas Incident - Hayward Update
Fixed.

From: [Redacted]
Sent: Tuesday, January 07, 2014 11:25 AM
To: UO EP Gas Incident Notify
Cc: [Redacted]
Subject: RE: CPUC Reportable Gas Incident - Hayward Update

UPDATE:

The leak was found at the riser service valve, which was fixed by the crew. A leak survey was conducted in the area and no LEL values were detected. Gas service to [Redacted] was restored at approximately 0956 hours.

If you have any questions, please let me know.

Thanks,

[Redacted]

Regulatory Compliance

Gas Operations | Pacific Gas and Electric

6111 Bollinger Canyon Road, 4th Floor

San Ramon, CA 94583

[Redacted]

Redacted

From: Redacted

Sent: Tuesday, January 07, 2014 10:41 AM

To: UO EP Gas Incident Notify

Cc: Redacted

Subject: CPUC Reportable Gas Incident

On January 7, 2014, at approximately 0821 hours, the Hayward Fire Department reported a gas odor inside Redacted located at Redacted in Hayward. The Fire Department shut off the gas and the California Highway Patrol evacuated approximately 700 people from the building. A Pacific Gas and Electric (PG&E) gas service representative was onsite at 0840 hours. At approximately 0845 hours, when the gas odor dissipated, the evacuated people were let back into the building. A PG&E leak survey crew is en route to conduct a leak survey to investigate the cause and the source of the gas odor. Channel 7 News was on the scene at approximately 0840 hours, making this incident reportable to the CPUC.

Redacted

Regulatory Compliance

Gas Operations | Pacific Gas and Electric

6111 Bollinger Canyon Road, 4th Floor

San Ramon, CA 94583

Redacted