

January 27, 2014

Via Email

Amol Patel  
Pacific Gas & Electric

**RE: Warning Notice for BUTTVL\_7\_UNIT 1**


Dear Mr. Patel,

Pursuant to Section 8.10 of the California Independent System Operator (ISO) Tariff, on 1/7/2014, the ISO performed a recertification test on BUTTVL\_7\_UNIT 1 to verify the resource's ability to deliver awarded or self-provided Non-spinning and Spinning Reserve within 10 minutes. In accordance with the ISO Operating Procedure 5370, a resource must deliver at least 90 percent of the requested energy within 10 minutes in order to pass the test.

This letter confirms that BUTTVL\_7\_UNIT 1 has passed the test conducted on 1/7/2014. The attached results show the resource's output during the test. The warning notice issued to BUTTVL\_7\_UNIT 1 on 7/24/2013 is no longer in effect.

If you have any questions about this letter, please contact Eric Kim at [ekim@caiso.com](mailto:ekim@caiso.com) or (916) 608-5949.

Sincerely,



Mike Russell  
Manager, Meter Engineering and Analysis  
SA