LA Testing 11652 Knott Street Unit F5, Garden Grove, CA 92841 Phone/Fax: (714) 828-4999 / (714) 828-4944 Iosalamitoslab@la	testing.com		LA Testing Order: CustomerID: CustomerPO: ProjectID:	331207972 32FOCU65
Attn: David Camarillo	Phone:	(951) 545-2495		
Focus Environmental Consulting	Fax:			
750 South Lincoln Avenue	Received:	05/30/12 1:00 PM	1	
Suite 104-166	Analysis Date:	5/31/2012		
Corona, CA 92882	Collected:	5/29/2012		
Project: Kern PP				

Test Report: Asbestos Analysis of Bulk Materials via EPA 600/R-93/116 and/or EPA 600/M4-82-020 Method(s) using Polarized Light Microscopy

		Non-Asbestos			stos	Asbestos	
Sample	Description	Appearance	%	Fibrous	% Non-Fibrous	% Type	
0529-1-01	Broiler Brick / NW	Black/Orange			100% Non-fibrous (other)	None Detected	
331207972-0001	Boiler	Non-Fibrous Heterogeneous					
0529-1-02	Broiler Brick / NE	Brown			100% Non-fibrous (other)	None Detected	
331207972-0002	Boiler	Non-Fibrous Homogeneous					
0529-1-03	Broiler Brick / SE	Tan			100% Non-fibrous (other)	None Detected	
331207972-0003	Boiler	Non-Fibrous Homogeneous					
0529-2-04	Mortor-Refractory	Red/Black/Beige		*******	100% Non-fibrous (other)	None Detected	
331207972-0004	/ NW Boiler	Non-Fibrous Heterogeneous					
0529-2-05	Mortor-Refractory	Brown/White			100% Non-fibrous (other)	None Detected	
331207972-0005	/ NE Boiler	Non-Fibrous Heterogeneous					
0529-2-06	Mortor-Refractory	Tan		an a	100% Non-fibrous (other)	None Detected	
331207972-0006	/ SE Boiler	Non-Fibrous Homogeneous					
0529-3-07	Boiler Insulation /	Brown	3%	Fibrous (other)	97% Non-fibrous (other)	None Detected	
331207972-0007	SE Boiler @ Outer Wall	Non-Fibrous Homogeneous					
0529-3-08	Boiler Insulation /	Brown	5%	Glass	90% Non-fibrous (other)	None Detected	
331207972-0008	NE Boiler @ Outer Wall	Non-Fibrous Homogeneous	5%	Fibrous (other)	. ,		

Analyst(s)

Christopher Kim (5) Krystyn Gonzales (3)

Derrick Tanner, Laboratory Manager or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used by the client to claim product certification, approval, or endorsement by NVLAP, NIST or any agency of the federal government. Non-friable organically bound materials present a problem matrix and therefore EMSL recommends gravimetric reduction prior to analysis. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request. Unless requested by the client, building materials manufactured with multiple layers (i.e. linoleum, wallboard, etc.) are reported as a single sample. Samples analyzed by LA Testing Garden Grove, CA NVLAP Lab Code 101384-0, CA ELAP 1406

Initial report from 05/31/2012 12:19:18