



Title: Utility Procedure WP4133-02 - Use of "New" Plat Maps for Cathodic Protection Area Assessment/Resurvey Procedures for Gas Distribution

Check all appropriate boxes

<input type="checkbox"/> SAFETY ALERT	<input checked="" type="checkbox"/> GAS	<input checked="" type="checkbox"/> DISTRIBUTION	<input type="checkbox"/> SUBSTATION ENGR.
<input checked="" type="checkbox"/> MANDATORY COMPLIANCE	<input type="checkbox"/> ELECTRIC	<input type="checkbox"/> TRANSMISSION	<input type="checkbox"/> TRANS/SUB M&C
<input type="checkbox"/> RECOMMENDED ACTIONS	<input type="checkbox"/> ESTIMATING	<input type="checkbox"/> OPERATIONS	<input type="checkbox"/> APPLICANT DESIGNER /
<input type="checkbox"/> INFORMATIONAL/CLARIFICATION	<input type="checkbox"/> MAPPING	<input type="checkbox"/> SERVICE	<input type="checkbox"/> CONSTRUCTION

Purpose

This Gas Information Bulletin revises Utility Procedure WP4133-02 to make it mandatory for Corrosion Mechanics to always obtain and use a new set of full size plat maps to verify that Cathodic Protection Area (CPA) maps are current when performing a CPA Assessment/Resurvey Procedures for Gas Distribution.

Communication Plan

An e-mail will be sent to all Division Gas T&R Supervisors to communicate this bulletin to the Corrosion Mechanics.

Division Gas T&R Supervisors will provide training regarding the contents of this bulletin to all employees performing Cathodic Protection Area Assessment/Resurvey Procedures for Gas Distribution.

The information contained in this bulletin will be included in WP4133-02 in addition to other revisions to be published in 2011.

Policy

Upon release of this bulletin, Corrosion Mechanics **must obtain a new set of full size plat maps** when completing Cathodic Protection Area Assessment/Resurvey Procedures for Gas Distribution. To ensure immediate compliance with this requirement, the following revisions to WP4133-02 are noted below.

WP4133-02, Attachment 1 "Initial CPA Assessment Worksheet"

Step 5 currently asks; "Does a review of the most recent plat sheets for the CPA indicate no jobs involving main installations, deactivations, or replacements occurring in the time period since the last CPA Resurvey of the area that would likely affect the CP levels within the CPA?"

Step 5 is now amended to read as follows:

"A new set of full size plat maps for the CPA must be obtained. Does a review of these plat maps indicate that there were no jobs involving main installations, deactivations or replacements occurring in the time period since the last CPA Resurvey that would likely affect the CP levels within the CPA?"

WP4133-02, Attachment 2 "CPA Field Resurvey Checklist"

Step 4 currently states "It is suggested that a new set of full size plat sheets for the CPA be used to validate the latest CPA maps in Step 5 below".

Step 4 is now amended to read as follows:

"A new set of full size plat maps for the CPA must be obtained and used to validate the latest pipeline profile of the CPA in Step 5 below."

Approved by:

[Redacted]

Date: 8/30/2010

Author: [Redacted]

If you have any questions about this bulletin, please call the employee(s) listed below:

Contact(s):

[Redacted]

[Redacted]

[Redacted]

LAN ID(s):

Phone(s):