



**Pacific Gas and
Electric Company**

Gas Information Bulletin

Title: Changes to Gas Transmission Station Maintenance and Addition of Leak Survey Form

Check all appropriate boxes

<input type="checkbox"/> SAFETY ALERT	<input checked="" type="checkbox"/> GAS	<input type="checkbox"/> DISTRIBUTION	<input type="checkbox"/> SUBSTATION ENGR.
<input checked="" type="checkbox"/> MANDATORY COMPLIANCE	<input type="checkbox"/> ELECTRIC	<input checked="" type="checkbox"/> TRANSMISSION	<input type="checkbox"/> TRANS./SUB. M&C
<input type="checkbox"/> RECOMMENDED ACTIONS	<input type="checkbox"/> ESTIMATING	<input type="checkbox"/> OPERATIONS	<input type="checkbox"/> APPLICANT DESIGNER /
<input checked="" type="checkbox"/> INFORMATIONAL/CLARIFICATION	<input type="checkbox"/> MAPPING	<input type="checkbox"/> SERVICE	<input type="checkbox"/> CONSTRUCTION

The purpose of this bulletin is to notify users of Utility Procedure TD-4430P-02, "Gas Transmission Stations Inspection, Testing, and Maintenance Procedures" of the following changes.

Change #1: Change the third paragraph in Step 4.8.1 to read:

For Becker pilots only, perform a Class A inspection annually (see Becker training manual). Perform a Class B inspection for cause

and

Change the title for Step 4.21 to read: "**Pilots (excludes Becker pilots)**"

Change #2: Change the title for Step 4.13 to read: "**Fire Protection Systems and Equipment**"

Also, Attachment 6, "Station Fire Protection Systems/Equipment Routine" is changed to conduct an annual review of the facility's Fire Pre-Plans (if one exists), and an annual inspection for designated fire walls and penetration seals (as designated in the facility's Fire Pre-Plans).

Change #3: A new Attachment 13 (Form TD-4430P-02-F08), "Gas Transmission Station Leak Survey Report" has been added to this procedure to document the results of the annual leak surveys at gas transmission stations.

Also, the following paragraph is added to Section 3 of the procedure.

7. Use form TD-4430P-02-F08 to document the results of the annual leak surveys at gas transmission stations.

The above changes are effective immediately, and must be implemented no later than 30 days upon publication of this bulletin. These changes will be incorporated into the next revision of this procedure.

Approved by:

[REDACTED]

Date: (06/16/2010)

Author: [REDACTED]

If you have any questions about this bulletin, please call the employee(s) listed below:

Contact(s): [REDACTED]
LAN ID(s): [REDACTED]
Phone(s): [REDACTED]

[REDACTED]