

July 1, 2011

David Lee, Utility Engineer
California Public Utilities Commission
505 Van Ness Avenue
San Francisco, CA 94102

Re: General Order 165 Report of Sierra Pacific Power Company (U 903-E)
and California Pacific Electric Company (U 933-E)

Dear Mr. Lee:


Enclosed please find the annual General Order (“GO”) 165 Report of Sierra Pacific Power Company (“Sierra”) and California Pacific Electric Company d/b/a Liberty Energy (“Liberty”) for calendar year 2010. This report is submitted in compliance with Section III of GO 165.

On October 28, 2010, the Commission issued Decision 10-10-017, which approved Sierra’s transfer to Liberty of the California electric distribution facilities and the Kings Beach Generating Station that Sierra had owned and operated. On January 1, 2011, the transfer of ownership was completed and Liberty began operations as the utility with responsibility for serving the electric customers within Sierra’s former California service territory.

As a result of the transfer of ownership, this report details the 2010 activities of Sierra and the 2011 activities of Liberty.

If additional information is required, please do not hesitate to call me at (775) 834-4686.

Sincerely,


Debbie Rice
Case Manager
Rates and Regulatory Affairs

Attachment

Sierra Pacific Power Company
ANNUAL GO 165 REPORT
 (California Service Territory)

Year - 2010

Year - 2011

		All Inspected Circuits										
		Units Scheduled for Inspection	Total Units Inspected	# of Units for Repair	% of Total Units for Repair	# of Units Repaired	% of Units Repaired	Units Scheduled for Repair	# of Units Repaired To Date	% of Units Repaired To Date		
Transformers												
Overhead		447	447	177	39.6%	16	9.0%	161	12	7.5%		
Underground		1	1	0	0.0%	0	0.0%	0	0	0.0%		
Padmounted		134	134	67	50.0%	47	70.1%	20	7	35.0%		
Switching / Protective Devices												
Overhead		178	178	53	29.8%	14	26.4%	39	0	0.0%		
Underground		0	0	0	0.0%	0	0.0%	0	0	0.0%		
Padmounted		8	8	3	37.5%	3	100.0%	0	0	0.0%		
Regulators / Capacitors / Reclosures												
Overhead		9	9	1	11.1%	0	0.0%	1	0	0.0%		
Underground		0	0	0	0.0%	0	0.0%	0	0	0.0%		
Padmounted		0	0	0	0.0%	0	0.0%	0	0	0.0%		
Distribution Conductors & Cable Miles												
		50.3	~	~	~	~	~	~	~	~		
Pole Line Hardware, Infractons, etc.												
		2439	2439	647	26.5%	464	71.7%	183	323	176.5%		
Vaults, Boxes & Manholes												
		4	4	1	25.0%	1	100.0%	0	0	0.0%		
Junction Enclosures												
		5	5	3	60.0%	3	100.0%	0	0	0.0%		
Wood Poles												
Wood Poles Inspected		2439	2439	~	~	~	~	~	~	~		
Wood Poles Intrusively Inspected		1380	1380	~	~	~	~	~	~	~		