

Order 41327058 (Redacted), San Bruno)

SAP Order Display (41327058)

PGE Order Processing (Display) : Order Su

OrderSummary Task Estimating Construction Materials

Legacy Order Header

41327058 Redacted

Order Type 6080 GAS DISTR EXPENSE

Notification 000104722316 Hold

Work Type 576 FIF-Maint-Corr-GMainVlv

User Status FICL srdy crdy Level 0

Priority E - Schd Compl Yr 0 Funded Y

MaintActType FIF Maint-Corr-G Main Vlv CCD N

Work Center COLMA Colma

Job Owner Reda Redacted

SAP Display Service Order Notification (41327058)

Display Service Notification: Gas Dsbm Corrective

Status Organization

Notification 104722316 GC VS/O Redacted

Status ATCO NOCO ORAS RELW CORR COMP

Serv order 41327058

Reference Info Location data Completion Dates Repair Report Tasks

Reported by

Reported by Red Notif date 06/11/2010 09:57:54

Start/End Dates

Malfunct start	08/02/2010 13:31:09	Required Start	06/14/2010 00:00:00
Malfunction end	00:00:00	Required End	08/16/2010 00:00:00

Completion Dates

Completn date	08/02/2010 13:32:36	Techinspectn by	Red
Reference date	07/22/2010 23:59:59	Techinspec on	07/22/2010

SAP Long Text Notes (41327058)

Display Longtext

06/16/2010 07:27:55 Redacted Re

PM# 41327058 6 JOB RCD IN CONST, FWD TO SUPV

C

07/10/2010 11:13:35 Redacted

41327058 6 - PGM1 EMAILED PERMIT REQUEST TO THE CITY OF SAN BRUNO. COMPLETED THE PERMIT TASK. COPY FILED IN PENDING PERMIT FILES & THE S/S HAS BEEN UPDATED.

C

07/12/2010 11:29:25 Redacted

41327058 6 - JOB PK6 BACK TO JOSE FLORES TO SCHEDULE PER D

C

07/13/2010 10:14:57 Redacted

***** Incident Code: INC15 - SICK/Fester. Notes from Scheduler: INC15 P D - Re 7/13 SCHED P D D 6/15

C

07/13/2010 12:01:29 Redacted

41327058 6 - REC'D PERMIT # 18-015 FROM THE CITY OF SAN BRUNO. PUT PERMIT IN OUT BOX FOR JOSE FLORES. COMPLETED THE PERMIT TASK. COPY FILED IN APPROVED PERMIT FILES & THE S/S HAS BEEN UPDATED.

C

07/21/2010 08:11:57 Redacted

PM# 41327058 6 JOB RCD IN CONST, FWD TO SUPV. Redacted

C

08/02/2010 13:30:29 Redacted

PM# 41327058 6, PER H. DAZA 7/22/10, PER Redacted VALVE NEEDS TO BE REPLACED, STEM VALVE COULD NOT BE REMOVED. PER HICKEY/SICKINGER 7/22/10 COULD NOT MAKE REPAIRS. STEM VALVE NEEDS TO BE REPLACED, SUBMITTED NEW GC NOTIF FOR WORK TO BE DONE.

Ln 1, Co 1 Ln 11 - Ln 44 of 44 lines