From: Lindh, Frank

Sent: 2/25/2011 7:08:57 PM

To: Clanon, Paul (paul.clanon@cpuc.ca.gov)

Cc: Cherry, Brian K (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=BKC7);

Horner, Trina (/O=PG&E/OU=CORPORATE/CN=RECIPIENTS/CN=TNHC);

Clanon, Paul (paul.clanon@cpuc.ca.gov); frank.lindh@cpuc.ca.gov

(frank.lindh@cpuc.ca.gov)

Bcc:

Subject: RE: Cold Weather this Weekend

Yes, thanks.

Thanks. Frank, want to meet there at 9:30?

On Feb 25, 2011, at 6:33 PM, "Horner, Trina" <TNHc@pge.com> wrote:

Hi Paul, yes they're still planning for injections tomorrow. If you show up at 9:30 a.m. the gas may not be flowing but the folks and all the equipment will be there, and Austin is expecting you and happy to show it all to you. They will decide tomorrow (based on forecast and tomorrow's actual loads, etc.) whether injections will also be needed on Sunday, so after tomorrow's injections they'll be prepping the tankers for re-filling, etc. so they're prepared for Sunday, just in case. Plenty to see.

Trina

From: Clanon, Paul [mailto:paul.clanon@cpuc.ca.gov]

Sent: Friday, February 25, 2011 6:18 PM

To: Cherry, Brian K

Cc: frank.lindh@cpuc.ca.gov; Horner, Trina **Subject:** Re: Cold Weather this Weekend

Trina, is this still happening weather-wise, and will there be anything left to see if we come at 9:30 tomorrow morning? Not sure what finishing the operations means.

On Feb 25, 2011, at 12:17 PM, "Cherry, Brian K" <BKC7@pge.com> wrote:

Am

From: Clanon, Paul [mailto:paul.clanon@cpuc.ca.gov]

Sent: Friday, February 25, 2011 12:15 PM

To: Cherry, Brian K; Lindh, Frank <frank.lindh@cpuc.ca.gov>

Subject: RE: Cold Weather this Weekend

Thanks. Frank wants to come too, and it would have to be tomorrow morning. Is the 930 in your note AM or PM?

From: Cherry, Brian K [mailto:BKC7@pge.com] **Sent:** Friday, February 25, 2011 10:18 AM

To: Clanon, Paul

Subject: FW: Cold Weather this Weekend

Here are your options.

From: Horner, Trina

Sent: Friday, February 25, 2011 10:12 AM

To: Cherry, Brian K

Subject: RE: Cold Weather this Weekend

Here's the deal:

Paul just needs to let us or Redacted know when he wants to come down and watch. Austin is the Supervising Engineer in charge of the LNG Peak Shaving set up today and the operations tomorrow. Best time to come is this afternoon, around 4:00 pm. That's when they're setting up and testing the equipment, and he will be able to get closer to the action. Paul can come tomorrow when they likely will deploy the LNG between 6-9 am, but that is not as good a time as people will not be able to get as close to the equipment as they want the operators to be able to focus on what they are doing. Or 9:30 tomorrow when they expect to finish the operations, will be another good time.

Location is at Redacted at the site of the old Potrero Power Plant. Personal Protective Safety

gear is required (orange vest & helmet); they will have extras on hand if Paul does not have his own.

Paul should call us or Austin directly to let us know when he'll be there so Austin can make sure he is there to meet Paul. Austin's cell phone # iRedacted Austin is aware Paul would like to come by and will just await further confirmation of timing.

Trina