

From: Cherry, Brian K
Sent: 10/24/2011 11:21:52 AM
To: 'pac@cpuc.ca.gov' (pac@cpuc.ca.gov); 'mlc@cpuc.ca.gov' (mlc@cpuc.ca.gov)
Cc: 'frl@cpuc.ca.gov' (frl@cpuc.ca.gov)
Bcc:
Subject: Fw: T117 Failure Pictures

Fyi

----- Original Message -----

From: Hartman, Sanford (Law)
Sent: Monday, October 24, 2011 11:19 AM
To: Cherry, Brian K
Subject: Fw: T117 Failure Pictures

----- Original Message -----

From: Garber, Stephen (Law)
Sent: Monday, October 24, 2011 10:21 AM
To: Malkin, Joseph M (Law); Hartman, Sanford (Law); Wilson, Michelle (Law); Jordan, Lise (Law); Redacted
Redacted
Cc: Redacted
Subject: FW: T117 Failure Pictures

Pictures of this morning's hydro test failure, the first such failure.
Line 300B in Bakersfield.
Don't know how quickly this can be repaired

-----Original Message-----

From: Campbell, Ben (NRD)
Sent: Monday, October 24, 2011 10:19 AM
To: Johnson, Kirk; Garber, Stephen (Law)
Subject: FW: T117 Failure Pictures

Pictures of the failure.

-----Original Message-----

From: Redacted
Sent: Monday, October 24, 2011 10:18 AM
To: 'Peter.Magallones@CH2M.com'; Moreland, Chauna; Mannie, Joel C; Campbell, Ben (NRD); Sanford, Angela; Redacted Redacted
Cc: Redacted

Subject: T117

Here are the pictures from T117

-----Original Message-----

From: [Redacted]

Sent: Monday, October 24, 2011 9:55 AM

To: [Redacted]

Subject: IMG00077-20111024-0952.jpg