

From: Cherry, Brian K
Sent: 11/25/2011 5:58:21 PM
To: 'mlc@cpuc.ca.gov' (mlc@cpuc.ca.gov); 'pac@cpuc.ca.gov' (pac@cpuc.ca.gov)
Cc:
Bcc:
Subject: Fw: THIRD PARTY FATALITY 11/25 - OAK RUN, CA

More info.

From: Kiraly, Gregory
Sent: Friday, November 25, 2011 05:54 PM
To: Williams, Geisha; Cherry, Brian K
Subject: Fw: THIRD PARTY FATALITY 11/25 - OAK RUN, CA

A bit more detail.

From: Redacted
Sent: Friday, November 25, 2011 05:20 PM
To: Kiraly, Gregory; Lemler, Gregg; Myers, Christopher
Subject: Fw: THIRD PARTY FATALITY 11/25 - OAK RUN, CA

Fyi...some additional information on the event.

From: Redacted
Sent: Friday, November 25, 2011 02:03 PM
To: Redacted; Swanson, Michael
Cc:
Subject: Fw: THIRD PARTY FATALITY 11/25 - OAK RUN, CA

Barry
Mike

Additional details on the car pole/fatality last night.

Redacted

From: Redacted
Sent: Friday, November 25, 2011 01:45 PM
To: Redacted; Mar, Anthony
Redacted
Subject: THIRD PARTY FATALITY 11/25 - OAK RUN, CA

All,

ILIS EVENT LOG # 11-0077959

FNL: 00:15

CIRCUIT: DESCHUTES 1101

AFFECTED SOURCE SIDE DEVICE: LR 1580

CUSTOMERS AFFECTED: 360

CAUSE: 3RD PARTY CAR-POLE ACCIDENT

LOCATION: 1 SPAN SOURCE SIDE OF 13609 OAK RUN ROAD. OAK RUN, CA

BRIEF DESCRIPTION: At 00:15, a Hi-Low Voltage tag came in via OIS and was dispatched to a Redding T-man at 00:19. A local Redding area lineman who lives in the Oak Run area contacted the North Valley Control Center Operator at 00:39 to report the car pole. The Unknown Premise Tag of wire down came in at 00:51. The Redding T-man was on site at 01:18 and began the process of making the area safe. From field accounts it was confirmed that third party struck utility pole causing 1 span of primary conductor to fall to the ground. The wire pulled free from a connection and fell away from the normal source that is why LR 1580 did not trip. From all accounts, it's believed, that the third party was fatally injured when he tried to get out of his vehicle and stepped on the downed primary conductor. The other victim was also complaining of electric shock but was taken in to custody by CHP due to intoxication. The Redding T-man has the CHP incident report. At 03:10, CPUC Rep Richard Jones was notified of event. All repairs were complete at 07:17 this morning. I believe all material from event are located at the Redding Service Center. For any other information please feel free to give me a call on my cell.

Thanks,

Redacted

North Valley Control Center Supervisor

Office: 8-750-4382/530-896-4382

Cell: 530-228-9799