

From: Cherry, Brian K  
Sent: 12/19/2011 7:14:04 PM  
To: 'fer@cpuc.ca.gov' (fer@cpuc.ca.gov)  
Cc:  
Bcc:  
Subject: Fw: H-1111 Update 3

FYI.

**From:** [Redacted]  
**Sent:** Monday, December 19, 2011 07:09 PM  
**To:** SF\_Update  
**Subject:** Re: H-1111 Update 3

Power to Candlestick Park has been restored. Cause for second outage is unknown at this time but does not appear to be due to loss of a PG&E source.

The Park is currently being supported by H1103 while repairs are being made to the wire down on H1111.

[Redacted]

**From:** [Redacted]  
**Sent:** Monday, December 19, 2011 06:53 PM  
**To:** SF\_Update  
**Subject:** RE: H-1111 Update 3

All,

We have confirmed one phase of overhead wire down at Ingerson just East of Bill Walsh Drive. M&C crew enroute and will make repairs. Area has been made safe for the public and no third party incident.

We also have confirmed a second interruption has occurred at Candlestick Park, cause for the second interruption is unknown at this time.

IC for this event is [Redacted] I will support Ops Chief role from the wire down location.

SF OEC is being fully activated.

[Redacted]

---

**From:** [Redacted]  
**Sent:** Monday, December 19, 2011 6:31 PM  
**To:** SF\_Update

**Subject:** RE: H-1111 Update 3

All,

At 1719 we experienced a momentary interruption on **H 1106** impacting Candlestick Park. We are continuing to investigate this power interruption but currently it is unknown if the interruption was due to PG&E or Candlestick Park equipment. No public injuries or third party damage have been reported.

**Operations Supervisor** is currently leading an investigation into what exactly happened during the event and gathering data.

**Restoration Supervisor** has multiple Tmen and Cablemen investigating the field conditions at Candlestick Park on Jamestown Drive. These employees are being supported by SFPD and will remain on-site throughout the game (as planned) to support any needed response actions.

**Substation Maintenance Supervisor** is in direct contact with the Candlestick Park Lead Technician assessing the situation. We also have a PG&E Electrician on-site at the Park available to provide any mutual aid assistance that may be requested.

**M&C Supervisor** has both an underground and overhead crew already staged and available to support any needed repairs.

**External Communications and ES&S** are proactively providing information as needed on the details of this outage.

**GovRel** has already been in contact with City OES and the Mayor's Office.

Our next update will be provided once we have confirmed exactly what happened to cause this power interruption, San Francisco OEC remains open as planned.

Jason

---

**From:** Redacted

**Sent:** Monday, December 19, 2011 5:51 PM

**To:** SF\_Update

**Subject:** FW: H-1111 Update 1

All:

Still at this time we have no update on the cause. More to follow.

Redacted

---

**From:** Redacted

**Sent:** Monday, December 19, 2011 5:44 PM

**To:** SF\_Update

**Subject:** H-1111

We received reports that we lost the H-1111 at candlestick park and the ATS did not transfer. Contacted the owner to work with them on the ATS. DO reports that the power is back at this time cause unknown. We have an electrician on the way.

No report of any incidents at this time.

More to follow.

Redacted